



Western Regional Office
721 N. Capitol Avenue, Suite 3
Lansing, MI 48906

December 21, 2017

Ingham County Land Bank Authority
ATTN: Roxanne Case

RE: Letter of Finding for Dwellings Unfit to Enter (Asbestos/Hazardous Material Surveys)

On this date (12/03/2017), ETC attempted to access the following address to complete an asbestos and hazardous material survey (630 S. Francis Ave, Lansing, MI).

However, due to warnings posted on the property from the Lansing Fire Department, Fire Marshal's Office- Code Enforcement Section, interior access was deemed impossible based on legal and safety restrictions. Consequently, ETC's inspectors only performed exterior testing, where possible and appropriate, at this dwelling.

Based on current state regulations any interior construction materials that may be present in this dwelling must be labeled and disclosed as "assumed ACM", although further testing may be used to dispute that assumption once access to the unit can be safely provided. Should these conditions be remedied and safe access is permitted, ETC will make every effort to conduct the inspection in a timely and compliant manner.

Please feel free to contact me directly with any questions or requests for more information; we stand ready to assist you with your continuing efforts to improve neighborhoods in Ingham County.

Sincerely,

Bryan M. Dryer, Executive Director
The ETC Group
(517)455-3448 (mobile)
bryan.dryer@2etc.com



Andy Schor, Mayor

CITY OF LANSING
Department of Economic Development and Planning

316 N. Capitol Ave., Suite C-1 – Lansing, MI 48933-1238

(517) 483-4355 – Fax (517) 377-0169

Brian McGrain, Director

www.LansingMi.gov

Office of Building Safety
Unsafe Structures Notice

February 28, 2018

Ingham County Land Bank
Fast Track Authority
3024 Turner Street
Lansing, Michigan 48906

Regarding: 630 South Francis Street
Parcel: #33-01-01-14-380-171

Dear ICLB,


This letter is in regard to the unsafe structure and unsafe site conditions at the aforementioned address. After a review of the site and structure this office has declared this site, structure and Use (R-3), unsafe to occupy in any part and is in structural failure. Therefore the site shall be properly secured to prevent anyone from entry and the structure shall be made safe or removed as stated herein. It is imperative and time is of the essence that steps be taken to address these issues. To ensure the health, safety and welfare for neighbors and the public, the City of Lansing and the State of Michigan requires that the building and site be protected, repaired and/or removed immediately.

This letter shall serve as notice that the property shall be made safe as set forth by the STILLE-DEROSSETT-HALE- SINGLE STATE CONSTRUCTION CODE ACT, Act 230 of 1972 known as the Michigan Building Code 2015 with amendments, in particular section 116.1 of the Michigan Building Code 2015; “Structures or existing equipment that are or hereafter become unsafe, insanitary or deficient because of inadequate means of egress facilitates, inadequate light and ventilation, or which constitutes a fire hazard, or are otherwise dangerous to human life or the public welfare, or that involve illegal or improper occupancy or inadequate maintenance, shall be deemed unsafe an unsafe condition. Unsafe structures shall be taken down and removed or made safe, as the Building Official deems necessary and as provided for in this section. A vacant structure that is not secured against entry shall be deemed unsafe.”

It is our understanding that measures need to be implemented to abate the structural hazards. This office approves the implementation of any and all measures to abate said hazards as set forth by the code.

Should you have any questions please feel free to contact me at (517) 483-4365 or at Steve.Swan@lansingmi.gov or visit our City web site at cityoflansing.com

Thank you,

A handwritten signature in blue ink, appearing to read 'S. Swan', with a stylized flourish extending to the right.

Steven M. Swan, C.B.O.
Chief Building Inspector
City of Lansing, Michigan

PRE-DEMOLITION ENVIRONMENTAL INSPECTION SUMMARY REPORT

Prepared For:

Ingham County Land Bank
3024 Turner Street
Lansing, MI 48906

Parcel:	33-01-01-14-380-171
House No:	630 S Francis Ave, Lansing, MI 48912
Date Inspected:	12/3/2017
Inspected By:	Jake Gleason
Inspectors State Card #	A-49991

Building Information

No. Stories	1	Garage	No garage
Square Footage	700 SF	Garage Square Footage	NA
Basement Square Footage	400 SF	Garage Siding	NA
Siding	Vinyl, Wood	Garage Color	NA
Color	Yellow	Garage Shingles	NA
Roof Shingles	Asphalt	Electric (Gone)	Disconnected
Asbestos present	No	Gas (Gone)	Disconnected
Inaccessible areas	Interior—Deemed unsafe to enter Lansing Fire Department		



Pre-Demolition Environmental Inspection Summary Report

Parcel: 33-01-01-14-380-171
House No. 630 S Francis Ave, Lansing, MI 48912
Date Inspected: 12/3/2017

TABLE 1

HAZARDOUS MATERIALS

Material Description	Quantity & Units	Location
TV Screens, monitors	4	Shed

TIRE(s) REPORT

Material	Quantity & Units	Location
Bike tires	3	Shed

Pre-Demolition Environmental Inspection Summary Report

Parcel: 33-01-01-14-380-171
House No. 630 S Francis Ave, Lansing, MI 48912
Date Inspected: 12/3/2017

TABLE 2
SUSPECT ASBESTOS CONTAINING MATERIALS

Material #	Friable (F) / Non-Friable (NF)	Material Description	Material Location	Estimated Quantity	ACM Present
1	NF	House wrap, black	Exterior	1000	No
2	NF	Asphalt shingle, black	Exterior	1100	No


Table 2 - Is a summary of the materials that were sampled. Materials that test positive for asbestos have been bolded to make identification easier. Quantities that are listed are estimates only. It is the contractor's responsibility to verify all amounts of asbestos identified during the bid process.


Attachment:

Site Drawing

Exterior

33-01-01-14-380-171
630 S Francis Ave, Lansing, MI 48912
12/3/2017



 Sample Location

Please Note: This is a rough floor plan only. All items, (doorways, Windows, etc.) may not be included in this illustration. Also, room and component sizes are not drawn to scale.

Ingham County Land Bank
199844

Attachment:

Site Photographs

Representative Pictures of House/Property

Parcel: 33-01-01-14-380-171
House No. 630 S Francis Ave, Lansing, MI 48912
Date Inspected: 12/3/2017



Front of house/property



Side #1 of house/property



Back of house/property



Side #2 of house/property

Representative Pictures of House/Property

Parcel: 33-01-01-14-380-171
House No. 630 S Francis Ave, Lansing, MI 48912
Date Inspected: 12/3/2017



Shed

Representative Pictures of Hazardous Materials

Parcel:	33-01-01-14-380-171
House No.	630 S Francis Ave, Lansing, MI 48912
Date Inspected:	12/3/2017



TV Screen, monitors

Attachment:

Laboratory Analytical Results

ENVIRONMENTAL TESTING LABORATORIES, INC.



38900 HURON RIVER DRIVE, SUITE 200
ROMULUS, MICHIGAN 48174
(734) 955-6600
FAX: (734) 955-6604

To : Environmental Testing And Consulting Inc.
38900 Huron River Drive
Romulus, MI 48174

Project Location :
630 S Francis Ave, Lansing MI

Attention :

Client Project : 33-01-01-14-380-171

ETC Job : 199844

Report Date : 12/7/2017

Login #	Sample ID	Work Requested	Completed
634936	1A	Asbestos Analysis	12/07/2017
634937	1B	Asbestos Analysis	12/07/2017
634938	2A	Asbestos Analysis	12/07/2017
634939	2B	Asbestos Analysis	12/07/2017

Reviewed by:

Quality Assurance Coordinator

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
38900 Huron River Drive
Romulus, MI 48174

Location :
630 S Francis Ave, Lansing MI

ETC Job : 199844
Client Project : 33-01-01-14-380-171
Date Collected : 12/03/2017
Date Received : 12/05/2017
Date Analyzed : 12/07/2017

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
634936 1A E Side Above Entry Analyst: Daniel Agnew	House Wrap	Black Fibrous Homogenous	95% Cellulose	5% Other	None Detected
634937 1B W Side Above Entry Analyst: Daniel Agnew	House Wrap	Black Fibrous Homogenous	95% Cellulose	5% Other	None Detected
634938 2A E Side Above Entry Analyst: Daniel Agnew	Asphalt Shingle	Black Non-Fibrous Homogenous		100% Other	None Detected
634939 2B W Side Above Entry Analyst: Daniel Agnew	Asphalt Shingle	Black Non-Fibrous Homogenous	1% Cellulose	99% Other	None Detected



Lab Supervisor/Other Signatory



Analyst: Daniel Agnew

400 Point Count Results by EPA 600/R-93/116 PLM (denoted by "PC")
Item 198.1: PLM Methods for Identifying and Quantitating Asbestos in Bulk Samples
Item 198.6: PLM Methods for Identifying and Quantitating Asbestos in Non-Friable Organically Bound Bulk Samples
EPA 600/R-93/116: Method for Determination of Asbestos in Bulk Building Materials
EPA 600/M4-82-020: Interim Method for Determination of Asbestos in Bulk Insulation Samples

ETL, Inc. maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced without written approval by ETL, Inc. Test Method EPA 600/R-93-116 & EPA 600/M4-82/020 or NYSDOH-ELAP item 198.1 and/or 198.6 was used to analyze all samples. Matrix interference and/or resolution limits (i.e. detecting asbestos in non-friable organically bound materials) may yield false results in certain circumstances. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing. Interpretation and use of test results are the responsibility of the client. ETL, Inc. is not responsible for the accuracy of the results when requested to physically separate and analyze layered samples. Any PLM results below 10% should be re-analyzed using the EPA recommended Point Count method. Any material that has greater than 1% asbestos content is considered to be an Asbestos Containing Material (ACM). These materials are regulated by both OSHA and the EPA and must be treated accordingly. Results are related to only to samples that were tested.

Asbestos Material Sampling Summary Sheet Miscellaneous materials

Revision date 5/7/2015

Job #: 100844		Building: 630 S. Francis, Lansing MI			Date: 12/3/17		
Material no.	Material Description	Friable (F) / Non-Friable (NF)	Sample Letter	Sample Location	Material Located throughout bldg (Please List all Rooms)	Quantity	Picture #
1	Material: House wrap	NF	A	E side above entry	ext	1000	1034
	Description: black		B	W side above entry			934
2	Material: Asphalt shingle	NF	A	E side above entry	ext	1100	937
	Description: black		B	W side above entry			938
	Material:		A				939
	Description:		B				
	Material:		A				
	Description:		B				
	Material:		A				
	Description:		B				
	Material:		A				
	Description:		B				
	Material:		A				
	Description:		B				

2 samples

2 of 2

Attachment:

Inspection Procedures

Pre-Demolition Environmental Inspection Procedures

HAZARDOUS MATERIALS INSPECTION

A table showing hazardous materials, above the household quantity limitations, found at the house is included as **Table 1: Hazardous Materials**. This table lists non-asbestos materials that may be hazardous and require special handling and disposal requirements. Items that might be in this category include: mercury switches, fluorescent lighting tubes and ballasts, halogen lights, Freon in refrigeration units, pesticides, herbicides, paints, solvents, etc.

Under the Resource Conservation and Recovery Act (RCRA) that addresses hazardous wastes, there is a residential household quantity exclusion. Materials are listed in Table I if they are present in quantities larger than what would typically be expected to be used and disposed in a normal household, and/or may require special handling and disposal requirements, such as: paints, solvents, adhesives, oils, tires, large circuit boards (such as televisions, computers, and security systems), prescription drugs, and syringes. On the other hand, if there were only household sized containers of maintenance, cleaning, non-prescription health and personal hygiene products, radios, and controllers present, as would be found in most homes, these materials would not be listed.

Fluorescent lighting systems have ballasts that have the potential to contain polychlorinated biphenyls (PCBs). Although PCBs are no longer commercially produced in the United States, they may be present in U.S. products that were produced prior to 1979, and may still be commercially available from other countries. Fluorescent bulbs, thermostats, and thermometers may contain mercury and can be treated as Universal Waste, which are streamlined standards for managing common types of hazardous waste.

If obtained, photographs of hazardous materials for the above referenced property are included in **Attachment: Site Photographs**.

ASBESTOS CONTAINING BUILDING MATERIAL INSPECTION

The property was inspected for the presence of asbestos-containing materials (ACMs) in order to meet the requirements of 40 CFR, Part 61, Subpart M, National Emissions Standards for Hazardous Air Pollutants (NESHAP).

Asbestos Inspection

The property was inspected for the presence of suspected ACMs. Typical building materials that may contain asbestos included drywall, plaster, stucco, floor tiles, roofing felt and shingles, ceiling tiles, insulation, pipe insulation, and duct insulation.

Sample Collection

Representative bulk samples of suspect asbestos containing building materials were randomly collected within each building area. The materials sampled were broken down into distinct homogenous (similar) materials. Homogenous material determination was based on the following criteria:

- Similar physical characteristics (same color and texture, etc.)
- Application (sprayed-on, troweled-on, assembly into a system etc.)
- Material function (Thermal insulation, floor tile, wallboard system etc.)

Pre-Demolition Environmental Inspection Procedures

At least two samples of each suspected asbestos containing material identified during the inspection was collected. For surfacing materials (sprayed and/or troweled on) a minimum of three samples were collected for areas that contained less than 1000 square feet of the material; 5 samples were collected for materials 1000 to 5000 square feet, and 7 samples were taken for areas greater than 5000 square feet. A Michigan Accredited Asbestos Inspector collected representative samples of each suspected ACM. Each sample was placed into a sealed plastic bag and labeled. A description of the material and location of the sample collected was recorded in the field notes. The total quantity of each suspected ACM was estimated and recorded in the field notes.

A listing of suspect ACMs at this property that were sampled and sent to the laboratory for analysis is included in **Table 2**. A copy of a floor plan showing sample locations is included in **Attachment: Site Drawing**.

Laboratory Analysis / Results

Each sample of suspect ACM collected at this property was analyzed for asbestos content using polarized light microscopy (PLM) by a NVLAP and NIST accredited laboratory in accordance with 40 CFR Ch. I (1-1-87 Edition) Part 763, Subpart F, Appendix A, pp. 293-299. Asbestos containing materials are defined as materials that contain greater than one percent (>1%) asbestos.

Each sample collected for analysis was delivered to either IATL (International Asbestos Testing Laboratories), 9000 Commerce Parkway, Suite B, Mt. Laurel, NJ 08054, ETL (Environmental Testing Laboratories), 38900 W. Huron River Drive, Suite 200, Romulus, MI 48174, and/or ACM Engineering & Environmental Services, 26598 US Highway 20 West, South Bend, IN 46628. Laboratory results are included in **Attachment: Laboratory Analytical Results**.

SIGNATURE

This report was prepared based on the site conditions that existed at the time of the inspection, sample collection, and the laboratory analytical results.



Prepared by: _____

Jake Gleason, Michigan Certified Asbestos Inspector (s)

Michigan Accreditation Number (s) A-49991

PRE-DEMOLITION ENVIRONMENTAL INSPECTION SUMMARY REPORT

Prepared For:

Ingham County Land Bank
3024 Turner Street
Lansing, MI 48906

Parcel:	33-01-01-22-279-191
House No:	1107 Regent St, Lansing, MI 48912
Date Inspected:	11/28/2017
Inspected By:	Jake Gleason
Inspectors State Card #	A-49991

Building Information			
No. Stories	1	Garage	Detached
Square Footage	600 SF	Garage Square Footage	300 SF
Basement Square Footage	600 SF	Garage Siding	Wood
Siding	Wood, Vinyl	Garage Color	White
Color	Cedar, White	Garage Shingles	Asphalt Shingle
Roof Shingles	Asphalt Shingle	Electric (Gone)	Disconnected
Asbestos present	YES	Gas (Gone)	Disconnected
Inaccessible areas			



Pre-Demolition Environmental Inspection Summary Report

Parcel: 33-01-01-22-279-191
House No. 1107 Regent St, Lansing, MI 48912
Date Inspected: 11/28/2017

TABLE 1

HAZARDOUS MATERIALS

Material Description	Quantity & Units	Location
Hot Water Heater	1	Room 9
Refrigerator	1	Room 5
Electronics	1	Room 3

TIRE(s) REPORT

Material	Quantity & Units	Location
Tires	1	Exterior

Pre-Demolition Environmental Inspection Summary Report

Parcel: 33-01-01-22-279-191
 House No. 1107 Regent St, Lansing, MI 48912
 Date Inspected: 11/28/2017


TABLE 2
SUSPECT ASBESTOS CONTAINING MATERIALS

Material #	Friable (F) / Non-Friable (NF)	Material Description	Material Location	Estimated Quantity	ACM Present
1	F	Drywall, white	Throughout	3100 SF	No
2	F	Mud and tape, white	Throughout	3100 SF	No
3	NF	12x12 Peel and Stick, green	Room 1	100 SF	No
4	NF	Rubber pad, black	Room 3, 4, 7	300 SF	No
5	NF	9x9 Tile, red	Room 5	225 SF	YES
6	F	Mastic, black (under 5)	Room 5	225 SF	No
7	NF	Linoleum, yellow and red	Room 5	225 SF	No
8	NF	Blown-in-insulation, grey	Throughout	3100 SF	No
9	NF	Floor leveler, grey	Room 6	75 SF	No
10	NF	12x12 Peel and stick, gold	Room 8	10 SF	No
11	NF	Poured concrete, grey	Room 9	480 SF	No
12	NF	Cinder block mortar, grey	Room 8, 9	500 SF	No
13	F	Sink undercoat, grey	Room 5	4 SF	YES
14	F	House wrap, black	Exterior	1500 SF	No
15	F	Asphalt shingle, black	Exterior	2000 SF	No

Table 2 - Is a summary of the materials that were sampled. Materials that test positive for asbestos have been bolded to make identification easier. Quantities that are listed are estimates only. It is the contractor's responsibility to verify all amounts of asbestos identified during the bid process.

Attachment:

Site Drawing




 Sample Location


Please Note: This is a rough floor plan only. All items, (doorways, Windows, etc.) may not be included in this illustration. Also, room and component sizes are not drawn to scale.

Basement

33-01-01-22-279-191
1107 Regent St, Lansing, MI 48912
11/28/2017



Garage



 Sample Location

Please Note: This is a rough floor plan only. All items, (doorways, Windows, etc.) may not be included in this illustration. Also, room and component sizes are not drawn to scale.

Ingham County Land Bank
199860

Attachment:

Site Photographs

Representative Pictures of House/Property

Parcel: 33-01-01-22-279-191
House No. 1107 Regent St, Lansing, MI 48912
Date Inspected: 11/28/2017



Front of house/property



Side #1 of house/property



Back of house/property



Side #2 of house/property

Representative Pictures of House/Property

Parcel:	33-01-01-22-279-191
House No.	1107 Regent St, Lansing, MI 48912
Date Inspected:	11/28/2017



Garage

Representative Pictures of Hazardous Materials

Parcel: 33-01-01-22-279-191
House No. 1107 Regent St, Lansing, MI 48912
Date Inspected: 11/28/2017



Refrigerator



Tire

Representative Pictures of Asbestos Containing Materials

Parcel: 33-01-01-22-279-191
House No. 1107 Regent St, Lansing, MI 48912
Date Inspected: 11/28/2017



9x9 Floor Tile



Sink Undercoat

Attachment:

Laboratory Analytical Results

ENVIRONMENTAL TESTING LABORATORIES, INC.



38900 HURON RIVER DRIVE, SUITE 200
ROMULUS, MICHIGAN 48174
(734) 955-6600
FAX: (734) 955-6604

To : Environmental Testing And Consulting Inc.
38900 Huron River Drive
Romulus, MI 48174

Project Location :
1107 Regent St, Lansing, MI

Attention :

Client Project : 33-01-01-22-279-191

ETC Job : 199860
Report Date : 12/7/2017

Login #	Sample ID	Work Requested	Completed
633591	01A	Asbestos Analysis	12/07/2017
633592	01B	Asbestos Analysis	12/07/2017
633593	02A	Asbestos Analysis	12/07/2017
633594	02B	Asbestos Analysis	12/07/2017
633595	03A	Asbestos Analysis	12/07/2017
633596	03B	Asbestos Analysis	12/07/2017
633597	04A	Asbestos Analysis	12/07/2017
633598	04B	Asbestos Analysis	12/07/2017
633599	05A	Asbestos Analysis	12/07/2017
633600	05B	Asbestos Analysis	12/07/2017
633601	06A	Asbestos Analysis	12/07/2017
633602	06B	Asbestos Analysis	12/07/2017
633603	07A	Asbestos Analysis	12/07/2017
633604	07B	Asbestos Analysis	12/07/2017
633605	08A	Asbestos Analysis	12/07/2017
633606	08B	Asbestos Analysis	12/07/2017
633607	09A	Asbestos Analysis	12/07/2017
633608	09B	Asbestos Analysis	12/07/2017
633609	10A	Asbestos Analysis	12/07/2017
633610	10B	Asbestos Analysis	12/07/2017

This report is intended for use solely by the individual or entity to which it is addressed. This report may not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government. It may contain information that is privileged, confidential and otherwise exempt by law from disclosure. If the reader of this information is not the intended recipient or an employee of its intended recipient, you are herewith notified that any dissemination, distribution or copying of this information is strictly prohibited. If you have received this information in error, please notify ETL immediately. Thank you.

Login #	Sample ID	Work Requested	Completed
633611	11A	Asbestos Analysis	12/07/2017
633612	11B	Asbestos Analysis	12/07/2017
633613	12A	Asbestos Analysis	12/07/2017
633614	12B	Asbestos Analysis	12/07/2017
633615	13A	Asbestos Analysis	12/07/2017
633616	13B	Asbestos Analysis	12/07/2017
633617	14A	Asbestos Analysis	12/07/2017
633618	14B	Asbestos Analysis	12/07/2017
633619	15A	Asbestos Analysis	12/07/2017
633620	15B	Asbestos Analysis	12/07/2017

Reviewed by:



Quality Assurance Coordinator

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
 38900 Huron River Drive
 Romulus, MI 48174

Location :
 1107 Regent St, Lansing, MI

ETC Job : 199860
Client Project : 33-01-01-22-279-191
Date Collected : 11/28/2017
Date Received : 12/01/2017
Date Analyzed : 12/07/2017

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
633591 01A Center Ceiling RM 1 Analyst: Ian McCusker	Drywall	White Non-Fibrous Homogenous	5% Cellulose	95% Other	None Detected
633592 01B W Wall entry RM 2 Analyst: Ian McCusker	Drywall	White Non-Fibrous Homogenous	8% Cellulose	92% Other	None Detected
633593 02A SE Corner RM 1 Layer-1 Analyst: Ian McCusker	Mud	White Non-Fibrous Homogenous	3% Cellulose	97% Other	None Detected
633593 02A SE Corner RM 1 Layer-2 Analyst: Ian McCusker	Tape	White Fibrous Homogenous	70% Cellulose	30% Other	None Detected
633594 02B N Wall RM 2 Layer-1 Analyst: Ian McCusker	Mud	White Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
633594 02B N Wall RM 2 Layer-2 Analyst: Ian McCusker	Tape	White Fibrous Homogenous	15% Cellulose	85% Other	None Detected
633595 03A W Entry RM 1 Analyst: Ian McCusker	12x12 Peel & Stick	Green Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected

ETL, Inc. maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced without written approval by ETL, Inc. Test Method EPA 600/R-93-116 & EPA 600/M4-82/020 or NYSDOH-ELAP item 198.1 and/or 198.6 was used to analyze all samples. Matrix interference and/or resolution limits (i.e. detecting asbestos in non-friable organically bound materials) may yield false results in certain circumstances. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing. Interpretation and use of test results are the responsibility of the client. ETL, Inc. is not responsible for the accuracy of the results when requested to physically separate and analyze layered samples. Any PLM results below 10% should be re-analyzed using the EPA recommended Point Count method. Any material that has greater than 1% asbestos content is considered to be an Asbestos Containing Material (ACM). These materials are regulated by both OSHA and the EPA and must be treated accordingly. Results are related to only to samples that were tested.

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
 38900 Huron River Drive
 Romulus, MI 48174

Location :
 1107 Regent St, Lansing, MI

ETC Job : 199860
Client Project : 33-01-01-22-279-191
Date Collected : 11/28/2017
Date Received : 12/01/2017
Date Analyzed : 12/07/2017

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
633596 03B E Entry RM 1 Analyst: Ian McCusker	12x12 Peel & Stick	Green Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
633597 04A W Entry RM 3 Analyst: Ian McCusker	Rubber Membrane	Black Non-Fibrous Homogenous	30% Cellulose	70% Other	None Detected
633598 04B W Entry RM 3 Analyst: Ian McCusker	Rubber Membrane	Black Non-Fibrous Homogenous	18% Cellulose	82% Other	None Detected
633599 05A N Entry RM 5 Analyst: Ian McCusker	9x9 Floor Tile	Red Non-Fibrous Homogenous	1% Cellulose	97% Other	2% Chrysotile
633600 05B N Entry RM 5 Analyst: Ian McCusker		Not Analyzed			
633601 06A N Entry RM 5 Analyst: Ian McCusker	Mastic	Black Non-Fibrous Homogenous	7% Cellulose	93% Other	None Detected
633602 06B N Entry RM 5 Analyst: Ian McCusker	Mastic	Black Non-Fibrous Homogenous	11% Cellulose	89% Other	None Detected

ETL, Inc. maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced without written approval by ETL, Inc. Test Method EPA 600/R-93-116 & EPA 600/M4-82/020 or NYSDOH-ELAP item 198.1 and/or 198.6 was used to analyze all samples. Matrix interference and/or resolution limits (i.e. detecting asbestos in non-friable organically bound materials) may yield false results in certain circumstances. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing. Interpretation and use of test results are the responsibility of the client. ETL, Inc. is not responsible for the accuracy of the results when requested to physically separate and analyze layered samples. Any PLM results below 10% should be re-analyzed using the EPA recommended Point Count method. Any material that has greater than 1% asbestos content is considered to be an Asbestos Containing Material (ACM). These materials are regulated by both OSHA and the EPA and must be treated accordingly. Results are related to only to samples that were tested.

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
 38900 Huron River Drive
 Romulus, MI 48174

Location :
 1107 Regent St, Lansing, MI

ETC Job : 199860
Client Project : 33-01-01-22-279-191
Date Collected : 11/28/2017
Date Received : 12/01/2017
Date Analyzed : 12/07/2017

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
633603 07A West Entry RM 5 Analyst: Ian McCusker	Linoleum	Yellow/Red Non-Fibrous Homogenous	7% Cellulose	93% Other	None Detected
633604 07B N Wall RM 5 Analyst: Ian McCusker	Linoleum	Yellow/Red Non-Fibrous Homogenous	6% Cellulose	94% Other	None Detected
633605 08A S Ceiling RM 8 Analyst: Ian McCusker	Blown Insulation	Grey Fibrous Homogenous	100% Cellulose		None Detected
633606 08B S Ceiling RM 8 Analyst: Ian McCusker	Blown Insulation	Grey Fibrous Homogenous	100% Cellulose		None Detected
633607 09A Entry RM 6 Analyst: Ian McCusker	Floor Leveler	Grey Non-Fibrous Homogenous	3% Cellulose	97% Other	None Detected
633608 09B Entry RM 6 Analyst: Ian McCusker	Floor Leveler	Grey Non-Fibrous Homogenous	5% Cellulose	95% Other	None Detected
633609 10A Middle RM 8 Analyst: Ian McCusker	12x12 Peel & Stick	Gold Non-Fibrous Homogenous		100% Other	None Detected

ETL, Inc. maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced without written approval by ETL, Inc. Test Method EPA 600/R-93-116 & EPA 600/M4-82/020 or NYSDOH-ELAP item 198.1 and/or 198.6 was used to analyze all samples. Matrix interference and/or resolution limits (i.e. detecting asbestos in non-friable organically bound materials) may yield false results in certain circumstances. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing. Interpretation and use of test results are the responsibility of the client. ETL, Inc. is not responsible for the accuracy of the results when requested to physically separate and analyze layered samples. Any PLM results below 10% should be re-analyzed using the EPA recommended Point Count method. Any material that has greater than 1% asbestos content is considered to be an Asbestos Containing Material (ACM). These materials are regulated by both OSHA and the EPA and must be treated accordingly. Results are related to only to samples that were tested.

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
 38900 Huron River Drive
 Romulus, MI 48174

Location :
 1107 Regent St, Lansing, MI

ETC Job : 199860
Client Project : 33-01-01-22-279-191
Date Collected : 11/28/2017
Date Received : 12/01/2017
Date Analyzed : 12/07/2017

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
633610 10B Middle RM 8 Analyst: Ian McCusker	12x12 Peel & Stick	Gold Non-Fibrous Homogenous		100% Other	None Detected
633611 11A Middle RM 9 Analyst: Ian McCusker	Concrete	Grey Non-Fibrous Homogenous	1% Cellulose	99% Other	None Detected
633612 11B Middle RM 9 Analyst: Ian McCusker	Concrete	Grey Non-Fibrous Homogenous	1% Cellulose	99% Other	None Detected
633613 12A S Entry RM 8 Analyst: Ian McCusker	Cinder Block Mortar	Grey Non-Fibrous Homogenous	1% Cellulose	99% Other	None Detected
633614 12B S Entry RM 8 Analyst: Ian McCusker	Cinder Block Mortar	Grey Non-Fibrous Homogenous	7% Cellulose	93% Other	None Detected
633615 13A E Wall RM 5 Analyst: Ian McCusker	Sink Undercoat	Grey Non-Fibrous Homogenous		70% Other	30% Chrysotile
633616 13B E Wall RM 5 Analyst: Ian McCusker		Not Analyzed			

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
 38900 Huron River Drive
 Romulus, MI 48174


Location :
 1107 Regent St, Lansing, MI

ETC Job : 199860
 Client Project : 33-01-01-22-279-191
 Date Collected : 11/28/2017
 Date Received : 12/01/2017
 Date Analyzed : 12/07/2017

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
633617 14A S Middle Wall Analyst: Ian McCusker	House Wrap	Black Fibrous Homogenous	70% Cellulose	30% Other	None Detected
633618 14B S Middle Wall Analyst: Ian McCusker	House Wrap	Black Fibrous Homogenous	63% Cellulose	37% Other	None Detected
633619 15A NW Corner RM 10 Analyst: Ian McCusker	Asphalt Shingle	Black Non-Fibrous Homogenous	5% Cellulose	95% Other	None Detected
633620 15B NE Corner House Analyst: Ian McCusker	Asphalt Shingle	Black Non-Fibrous Homogenous	12% Cellulose	88% Other	None Detected



Lab Supervisor/Other Signatory



Analyst: Ian McCusker

400 Point Count Results by EPA 600/R-93/116 PLM (denoted by "PC")
 Item 198.1: PLM Methods for Identifying and Quantitating Asbestos in Bulk Samples
 Item 198.6: PLM Methods for Identifying and Quantitating Asbestos in Non-Friable Organically Bound Bulk Samples
 EPA 600/R-93/116: Method for Determination of Asbestos in Bulk Building Materials
 EPA 600/M4-82-020: Interim Method for Determination of Asbestos in Bulk Insulation Samples

ETL, Inc. maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced without written approval by ETL, Inc. Test Method EPA 600/R-93-116 & EPA 600/M4-82/020 or NYSDOH-ELAP item 198.1 and/or 198.6 was used to analyze all samples. Matrix interference and/or resolution limits (i.e. detecting asbestos in non-friable organically bound materials) may yield false results in certain circumstances. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing. Interpretation and use of test results are the responsibility of the client. ETL, Inc. is not responsible for the accuracy of the results when requested to physically separate and analyze layered samples. Any PLM results below 10% should be re-analyzed using the EPA recommended Point Count method. Any material that has greater than 1% asbestos content is considered to be an Asbestos Containing Material (ACM). These materials are regulated by both OSHA and the EPA and must be treated accordingly. Results are related to only to samples that were tested.

Asbestos Material Sampling Summary Sheet

Miscellaneous materials

Revision date 5/7/2015

Job #: 109860		Building: 1167 Regent, Lansing MI			Date: 11/29/17		
Material no.	Material Description	Friable (F) / Non-Friable (NF)	Sample Letter	Sample Location	Material Located throughout bldg (Please List all Rooms)	Quantity	Picture #
1	Material: Drywall	F	A	633 center ceiling rm 1 591	throughout	3100 sf	
	Description: white		B	w wall entry rm 2 592			
2	Material: mud tape	F	A	305 ^E corner rm 1 593	throughout	3100 sf	
	Description: white		B	n wall rm 2 594			
3	Material: 12x12 P+S	NF	A	w entry rm 1 595	1	100 sf	
	Description: green		B	e entry rm 1 596			
4	Material: rubber pad	NF	A	w ↓ entry rm 3 597	3,4,7	300 sf	
	Description: black		B	598			
5	Material: red 9x9 tile	NF	A	n entry ↓ rms 599	5	225 sf	
	Description: red		B	600			
6	Material: mastic (under)	F	A	601	5	225 sf	
	Description: black		B	602			
7	Material: linoleum	NF	A	west entry rms 603	5	225 sf	
	Description: yellow + red		B	n wall rms 604			
8	Material: Blown in insulation	NF	A	s ceiling ↓ rm 8 605	throughout	3100 sf	
	Description: grey		B	606			
9	Material: floor leveler	NF	A	entry ↓ rm 6 607	6	75 sf	
	Description: grey		B	608			
10	Material: 12x12 P+S	N	A	middle ↓ rms 609	8	10 sf	
	Description: grey		B	610			

2 samples

2 of 3

Asbestos Material Sampling Summary Sheet Miscellaneous materials

Revision date 5/7/2015

Job #: 194860		Building: 1107 Regent, Lansing MI			Date: 11/28/17		
Material no.	Material Description	Friable (F) / Non-Friable (NF)	Sample Letter	Sample Location	Material Located throughout bldg (Please List all Rooms)	Quantity	Picture #
11	Material: Poured concrete	NF	A	6033 middle rm 9 611	9	480 sf	
	Description: grey		B	612			
12	Material: cinder block mortar	NF	A	entry rm 8 613	8,9	500 sf	
	Description: grey		B	614			
13	Material: sink undercoat	F	A	e wall rm 5 615	5	4 sf	
	Description: grey		B	616			
14	Material: house wrap	F	A	s middle wall 617	ext	1500 sf	
	Description: black		B	618			
15	Material: asphalt shingle	F	A	NW corner rm 10 619	ext	2000 sf	
	Description: black		B	NE corner house 620			
	Material:		A				
	Description:		B				
	Material:		A				
	Description:		B				
	Material:		A				
	Description:		B				
	Material:		A				
	Description:		B				
	Material:		A				
	Description:		B				

Attachment:

Inspection Procedures

Pre-Demolition Environmental Inspection Procedures

HAZARDOUS MATERIALS INSPECTION

A table showing hazardous materials, above the household quantity limitations, found at the house is included as **Table 1: Hazardous Materials**. This table lists non-asbestos materials that may be hazardous and require special handling and disposal requirements. Items that might be in this category include: mercury switches, fluorescent lighting tubes and ballasts, halogen lights, Freon in refrigeration units, pesticides, herbicides, paints, solvents, etc.

Under the Resource Conservation and Recovery Act (RCRA) that addresses hazardous wastes, there is a residential household quantity exclusion. Materials are listed in Table I if they are present in quantities larger than what would typically be expected to be used and disposed in a normal household, and/or may require special handling and disposal requirements, such as: paints, solvents, adhesives, oils, tires, large circuit boards (such as televisions, computers, and security systems), prescription drugs, and syringes. On the other hand, if there were only household sized containers of maintenance, cleaning, non-prescription health and personal hygiene products, radios, and controllers present, as would be found in most homes, these materials would not be listed.

Fluorescent lighting systems have ballasts that have the potential to contain polychlorinated biphenyls (PCBs). Although PCBs are no longer commercially produced in the United States, they may be present in U.S. products that were produced prior to 1979, and may still be commercially available from other countries. Fluorescent bulbs, thermostats, and thermometers may contain mercury and can be treated as Universal Waste, which are streamlined standards for managing common types of hazardous waste.

If obtained, photographs of hazardous materials for the above referenced property are included in **Attachment: Site Photographs**.

ASBESTOS CONTAINING BUILDING MATERIAL INSPECTION

The property was inspected for the presence of asbestos-containing materials (ACMs) in order to meet the requirements of 40 CFR, Part 61, Subpart M, National Emissions Standards for Hazardous Air Pollutants (NESHAP).

Asbestos Inspection

The property was inspected for the presence of suspected ACMs. Typical building materials that may contain asbestos included drywall, plaster, stucco, floor tiles, roofing felt and shingles, ceiling tiles, insulation, pipe insulation, and duct insulation.

Sample Collection

Representative bulk samples of suspect asbestos containing building materials were randomly collected within each building area. The materials sampled were broken down into distinct homogenous (similar) materials. Homogenous material determination was based on the following criteria:

- Similar physical characteristics (same color and texture, etc.)
- Application (sprayed-on, troweled-on, assembly into a system etc.)
- Material function (Thermal insulation, floor tile, wallboard system etc.)

Pre-Demolition Environmental Inspection Procedures

At least two samples of each suspected asbestos containing material identified during the inspection was collected. For surfacing materials (sprayed and/or troweled on) a minimum of three samples were collected for areas that contained less than 1000 square feet of the material; 5 samples were collected for materials 1000 to 5000 square feet, and 7 samples were taken for areas greater than 5000 square feet. A Michigan Accredited Asbestos Inspector collected representative samples of each suspected ACM. Each sample was placed into a sealed plastic bag and labeled. A description of the material and location of the sample collected was recorded in the field notes. The total quantity of each suspected ACM was estimated and recorded in the field notes.

A listing of suspect ACMs at this property that were sampled and sent to the laboratory for analysis is included in **Table 2**. A copy of a floor plan showing sample locations is included in **Attachment: Site Drawing**.


Laboratory Analysis / Results

Each sample of suspect ACM collected at this property was analyzed for asbestos content using polarized light microscopy (PLM) by a NVLAP and NIST accredited laboratory in accordance with 40 CFR Ch. I (1-1-87 Edition) Part 763, Subpart F, Appendix A, pp. 293-299. Asbestos containing materials are defined as materials that contain greater than one percent (>1%) asbestos.

Each sample collected for analysis was delivered to either IATL (International Asbestos Testing Laboratories), 9000 Commerce Parkway, Suite B, Mt. Laurel, NJ 08054, ETL (Environmental Testing Laboratories), 38900 W. Huron River Drive, Suite 200, Romulus, MI 48174, and/or ACM Engineering & Environmental Services, 26598 US Highway 20 West, South Bend, IN 46628. Laboratory results are included in **Attachment: Laboratory Analytical Results**.

SIGNATURE

This report was prepared based on the site conditions that existed at the time of the inspection, sample collection, and the laboratory analytical results.



Prepared by: _____

Jake Gleason, Michigan Certified Asbestos Inspector (s)

Michigan Accreditation Number (s) A-49991

PRE-DEMOLITION ENVIRONMENTAL INSPECTION SUMMARY REPORT

Prepared For:

Ingham County Land Bank
3024 Turner Street
Lansing, MI 48906

Parcel:	33-01-01-22-226-331
House No:	943 MCCullough St, Lansing, MI, 48912
Date Inspected:	12/22/2017 & 2/15/2018
Inspected By:	Heather Davis & Jake Gleason
Inspectors State Card #	A-48908 & A-49991

Building Information			
No. Stories	2	Garage	No Garage
Square Footage	1008 SF	Garage Square Footage	NA
Basement Square Footage	500 SF	Garage Siding	NA
Siding	Vinyl	Garage Color	NA
Color	White	Garage Shingles	NA
Roof Shingles	Asphalt	Electric (Gone)	Disconnected
Asbestos present	YES	Gas (Gone)	Disconnected
Inaccessible areas			



Pre-Demolition Environmental Inspection Summary Report

Parcel: 33-01-01-22-226-331
House No. 943 MCCullough St, Lansing, MI, 48912
Date Inspected: 12/22/2017 & 2/15/2018

TABLE 1

HAZARDOUS MATERIALS

Material Description	Quantity & Units	Location
----------------------	------------------	----------

None observed above household quantities		
--	--	--

TIRE(s) REPORT

Material	Quantity & Units	Location
----------	------------------	----------

None observed above household quantities		
--	--	--

Pre-Demolition Environmental Inspection Summary Report

Parcel: 33-01-01-22-226-331
 House No. 943 MCCullough St, Lansing, MI, 48912
 Date Inspected: 12/22/2017 & 2/15/2018

TABLE 2
SUSPECT ASBESTOS CONTAINING MATERIALS

Material #	Friable (F) / Non-Friable (NF)	Material Description	Material Location	Estimated Quantity	ACM Present
1	NF	Window glaze, white	Exterior (windows)	8 windows	YES
2	NF	House wrap, tan	Exterior (house)	3432 SF	No
3	NF	Shingle, grey	Exterior (house)	1008 SF	No
4	NF	Felt paper, black	Exterior (house)	1008 SF	No
5	NF	Window caulk, white	Exterior (house)	8 windows	No
6	F	Texture ceiling, white	Room 9	144 SF	No
7	NF	Plaster, grey	Room 7-9, 11-13	3500 SF	No
8	F	Duct wrap, brown	Throughout	325 SF	YES
9	F	Blown in insulation, grey	Throughout	5900 SF	No
10	F	Drywall, white	Room 1-6, 12	3900 SF	No
11	F	Mud, white	Room 1-6, 12	3900 SF	No
12	F	Tape, white	Room 1-6, 12	3900 SF	No
13	NF	12x12 Tile, white	Room 6	54 SF	No
14	NF	Mastic, yellow	Room 6	54 SF	No
15	NF	Poured concrete, grey	Room 14, 15	1200 SF	No


Table 2 - Is a summary of the materials that were sampled. Materials that test positive for asbestos have been bolded to make identification easier. Quantities that are listed are estimates only. It is the contractor's responsibility to verify all amounts of asbestos identified during the bid process.


Attachment:

Site Drawing


1st floor

33-01-01-22-226-331
943 MCCullough St, Lansing, MI, 48912
12/22/2017 & 2/15/2018



 Sample Location

Please Note: This is a rough floor plan only. All items, (doorways, Windows, etc.) may not be included in this illustration. Also, room and component sizes are not drawn to scale.




 Sample Location

Please Note: This is a rough floor plan only. All items, (doorways, Windows, etc.) may not be included in this illustration. Also, room and component sizes are not drawn to scale.

Basement

33-01-01-22-226-331
943 MCCullough St, Lansing, MI, 48912
12/22/2017 & 2/15/2018



 Sample Location

Please Note: This is a rough floor plan only. All items, (doorways, Windows, etc.) may not be included in this illustration. Also, room and component sizes are not drawn to scale.

Ingham County Land Bank
199858

Attachment:

Site Photographs

Representative Pictures of House/Property

Parcel: 33-01-01-22-226-331
House No. 943 MCCullough St, Lansing, MI, 48912
Date Inspected: 12/22/2017 & 2/15/2018



Front of house/property



Side #1 of house/property



Back of house/property



Side #2 of house/property

Representative Pictures of Asbestos Containing Materials

Parcel: 33-01-01-22-226-331

House No. 943 MCCullough St, Lansing, MI, 48912

Date Inspected: 12/22/2017 & 2/15/2018



Window glaze, white



Duct wrap, brown

Attachment:

Laboratory Analytical Results

ENVIRONMENTAL TESTING LABORATORIES, INC.



38900 HURON RIVER DRIVE, SUITE 200
ROMULUS, MICHIGAN 48174
(734) 955-6600
FAX: (734) 955-6604

REVISED REPORT

To : Environmental Testing And Consulting Inc.
38900 Huron River Drive
Romulus, MI 48174

Project Location :
943 McCullough St, Lansing, MI

Attention :

Client Project : 33-01-01-22-226-331

ETC Job : 199858

Report Date : 2/19/2018

Login #	Sample ID	Work Requested	Completed
643374	01A	Asbestos Analysis	12/26/2017
643375	01B	Asbestos Analysis	12/26/2017
643376	02A	Asbestos Analysis	12/26/2017
643377	02B	Asbestos Analysis	12/26/2017
643378	03A	Asbestos Analysis	12/26/2017
643379	03B	Asbestos Analysis	12/26/2017
643380	04A	Asbestos Analysis	12/26/2017
643381	04B	Asbestos Analysis	12/26/2017
643382	05A	Asbestos Analysis	12/26/2017
643383	05B	Asbestos Analysis	12/26/2017
687609	6A	Asbestos Analysis	12/26/2017
687610	6B	Asbestos Analysis	02/19/2018
687611	6C	Asbestos Analysis	02/19/2018
687612	7A	Asbestos Analysis	02/19/2018
687613	7B	Asbestos Analysis	02/19/2018
687614	7C	Asbestos Analysis	02/19/2018
687615	7D	Asbestos Analysis	02/19/2018
687616	7E	Asbestos Analysis	02/19/2018
687617	8A	Asbestos Analysis	02/19/2018
687618	8B	Asbestos Analysis	02/19/2018

This report is intended for use solely by the individual or entity to which it is addressed. This report may not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government. It may contain information that is privileged, confidential and otherwise exempt by law from disclosure. If the reader of this information is not the intended recipient or an employee of its intended recipient, you are herewith notified that any dissemination, distribution or copying of this information is strictly prohibited. If you have received this information in error, please notify ETL immediately. Thank you.

Login #	Sample ID	Work Requested	Completed
687619	8C	Asbestos Analysis	02/19/2018
687620	9A	Asbestos Analysis	02/19/2018
687621	9B	Asbestos Analysis	02/19/2018
687622	10A	Asbestos Analysis	02/19/2018
687623	10B	Asbestos Analysis	02/19/2018
687624	11A	Asbestos Analysis	02/19/2018
687625	11B	Asbestos Analysis	02/19/2018
687626	12A	Asbestos Analysis	02/19/2018
687627	12B	Asbestos Analysis	02/19/2018
687628	13A	Asbestos Analysis	02/19/2018
687629	13B	Asbestos Analysis	02/19/2018
687630	14A	Asbestos Analysis	02/19/2018
687631	14B	Asbestos Analysis	02/19/2018
687632	15A	Asbestos Analysis	02/19/2018
687633	15B	Asbestos Analysis	02/19/2018

Reviewed by:



Quality Assurance Coordinator

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
38900 Huron River Drive
Romulus, MI 48174

Location :
943 McCullough St, Lansing, MI

ETC Job : 199858
Client Project : 33-01-01-22-226-331
Date Collected : 12/22/2017
Date Received : 12/26/2017
Date Analyzed : 12/26/2017

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
643374 01A N Window Ext Analyst: Jessica Dilworth	Window Glaze	White Non-Fibrous Homogenous	2% Cellulose	95.25% Other	PC 2.75% Chrysotile
643375 01B E Window Ext Analyst: Jessica Dilworth		Not Analyzed			
643376 02A E Ext House Analyst: Jessica Dilworth	House Wrap	Brown Fibrous Homogenous	92% Cellulose	8% Other	None Detected
643377 02B S Ext House Analyst: Jessica Dilworth	House Wrap	Brown Fibrous Homogenous	92% Cellulose	8% Other	None Detected
643378 03A N Ext Roof Analyst: Jessica Dilworth	Shingle	Black Non-Fibrous Homogenous	20% Fiberglass 2% Cellulose	78% Other	None Detected
643379 03B W Ext Roof Analyst: Jessica Dilworth	Shingle	Black Non-Fibrous Homogenous	10% Fiberglass 2% Cellulose	88% Other	None Detected
643380 04A N Ext Roof Analyst: Jessica Dilworth	Felt Paper	Black Fibrous Homogenous	15% Cellulose	85% Other	None Detected

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
 38900 Huron River Drive
 Romulus, MI 48174

Location :
 943 McCullough St, Lansing, MI

ETC Job : 199858
Client Project : 33-01-01-22-226-331
Date Collected : 12/22/2017
Date Received : 12/26/2017
Date Analyzed : 12/26/2017

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
643381 04B W Ext Roof Analyst: Jessica Dilworth	Felt Paper	Black Fibrous Homogenous	15% Cellulose	85% Other	None Detected
643382 05A Window S Ext Analyst: Jessica Dilworth	Window Caulk	White Non-Fibrous Homogenous	1% Cellulose	99% Other	None Detected
643383 05B Window W Ext Analyst: Jessica Dilworth	Window Caulk	White Non-Fibrous Homogenous	1% Cellulose	99% Other	None Detected
687609 6A N Ceilling RM9 Analyst: Dave Cousino	Textured Ceiling	White Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
687610 6B S Ceiling RM9 Analyst: Dave Cousino	Textured Ceiling	White Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
687611 6C Middle Ceiling RM9 Analyst: Dave Cousino	Textured Ceiling	White Non-Fibrous Homogenous	1% Cellulose	99% Other	None Detected

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
 38900 Huron River Drive
 Romulus, MI 48174

Location :
 943 McCullough St, Lansing, MI

ETC Job : 199858
Client Project : 33-01-01-22-226-331
Date Collected : 02/15/2018
Date Received : 02/16/2018
Date Analyzed : 02/19/2018

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
687612 7A RM7 W Wall Layer-1 Analyst: Dave Cousino	Plaster	Grey Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
687612 7A RM7 W Wall Layer-2 Analyst: Dave Cousino	Skim	White Non-Fibrous Homogenous	1% Cellulose	99% Other	None Detected
687613 7B RM8 S Wall Layer-1 Analyst: Dave Cousino	Plaster	Grey Non-Fibrous Homogenous	3% Cellulose	97% Other	None Detected
687613 7B RM8 S Wall Layer-2 Analyst: Dave Cousino	Skim	White Non-Fibrous Homogenous	3% Cellulose	97% Other	None Detected
687614 7C RM9 E Wall Layer-1 Analyst: Dave Cousino	Plaster	Grey Non-Fibrous Homogenous	3% Cellulose	97% Other	None Detected
687614 7C RM9 E Wall Layer-2 Analyst: Dave Cousino	Skim	White Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
 38900 Huron River Drive
 Romulus, MI 48174

Location :
 943 McCullough St, Lansing, MI

ETC Job : 199858
Client Project : 33-01-01-22-226-331
Date Collected : 02/15/2018
Date Received : 02/16/2018
Date Analyzed : 02/19/2018

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
687615 7D RM11 N Wall Layer-1 Analyst: Dave Cousino	Plaster	Grey Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
687615 7D RM11 N Wall Layer-2 Analyst: Dave Cousino	Skim	White Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
687616 7E RM13 N Wall Layer-1 Analyst: Dave Cousino	Plaster	Grey Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
687616 7E RM13 N Wall Layer-2 Analyst: Dave Cousino	Skim	White Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
687617 8A RM8 Vent Analyst: Dave Cousino	Duct Wrap	Brown Fibrous Homogenous	60% Cellulose	20% Other	20% Chrysotile
687618 8B RM13 Vent Analyst: Dave Cousino		Not Analyzed			
687619 8C RM3 Vent Analyst: Dave Cousino		Not Analyzed			

ETL, Inc. maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced without written approval by ETL, Inc. Test Method EPA 600/R-93-116 & EPA 600/M4-82/020 or NYSDOH-ELAP item 198.1 and/or 198.6 was used to analyze all samples. Matrix interference and/or resolution limits (i.e. detecting asbestos in non-friable organically bound materials) may yield false results in certain circumstances. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing. Interpretation and use of test results are the responsibility of the client. ETL, Inc. is not responsible for the accuracy of the results when requested to physically separate and analyze layered samples. Any PLM results below 10% should be re-analyzed using the EPA recommended Point Count method. Any material that has greater than 1% asbestos content is considered to be an Asbestos Containing Material (ACM). These materials are regulated by both OSHA and the EPA and must be treated accordingly. Results are related to only to samples that were tested.



Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
38900 Huron River Drive
Romulus, MI 48174

Location :
943 McCullough St, Lansing, MI

ETC Job : 199858

Client Project : 33-01-01-22-226-331

Date Collected : 02/15/2018

Date Received : 02/16/2018

Date Analyzed : 02/19/2018

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
687620 9A RM8 S Wall Analyst: Dave Cousino	Blown Insulation	Grey Fibrous Homogenous	90% Cellulose	10% Other	None Detected
687621 9B RM7 W Wall Analyst: Dave Cousino	Blown Insulation	Grey Fibrous Homogenous	85% Cellulose	15% Other	None Detected
687622 10A RM3 W Wall Analyst: Dave Cousino	Drywall	White Non-Fibrous Homogenous	3% Cellulose	97% Other	None Detected
687623 10B RM5 S Wall Analyst: Dave Cousino	Drywall	White Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
687624 11A RM3 W Wall Analyst: Dave Cousino	Mud	White Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
687625 11B RM5 S Wall Analyst: Dave Cousino	Mud	White Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
687626 12A RM3 W Wall Analyst: Dave Cousino	Tape	White Non-Fibrous Homogenous	1% Cellulose	99% Other	None Detected

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
 38900 Huron River Drive
 Romulus, MI 48174

Location :
 943 McCullough St, Lansing, MI

ETC Job : 199858

Client Project : 33-01-01-22-226-331

Date Collected : 02/15/2018

Date Received : 02/16/2018

Date Analyzed : 02/19/2018

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
687627 12B RM5 S Wall Analyst: Dave Cousino	Tape	White Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
687628 13A RM6 Entry Analyst: Dave Cousino	12x12 Floor Tile	White Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
687629 13B RM6 N Wall Analyst: Dave Cousino	12x12 Floor Tile	White Non-Fibrous Homogenous	3% Cellulose	97% Other	None Detected
687630 14A RM6 Entry Analyst: Dave Cousino	Mastic	Yellow Non-Fibrous Homogenous	4% Cellulose	96% Other	None Detected
687631 14B RM6 N Wall Analyst: Dave Cousino	Mastic	Yellow Non-Fibrous Homogenous	3% Cellulose	97% Other	None Detected
687632 15A RM14 Middle Analyst: Dave Cousino	Poured Concrete	Grey Non-Fibrous Homogenous	3% Cellulose	97% Other	None Detected
687633 15B RM15 Middle Analyst: Dave Cousino	Poured Concrete	Grey Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
 38900 Huron River Drive
 Romulus, MI 48174

Location :
 943 McCullough St, Lansing, MI

ETC Job : 199858
Client Project : 33-01-01-22-226-331
Date Collected : 02/15/2018
Date Received : 02/16/2018
Date Analyzed : 02/19/2018

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
--------	-------------	------------	-----------	---------------	------------



Lab Supervisor/Other Signatory

David Cousino

Analyst: Dave Cousino

Jessica Dilworth

Analyst: Jessica Dilworth

400 Point Count Results by EPA 600/R-93/116 PLM (denoted by "PC")
 Item 198.1: PLM Methods for Identifying and Quantitating Asbestos in Bulk Samples
 Item 198.6: PLM Methods for Identifying and Quantitating Asbestos in Non-Friable Organically Bound Bulk Samples
 EPA 600/R-93/116: Method for Determination of Asbestos in Bulk Building Materials
 EPA 600/M4-82-020: Interim Method for Determination of Asbestos in Bulk Insulation Samples

ETL, Inc. maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced without written approval by ETL, Inc. Test Method EPA 600/R-93-116 & EPA 600/M4-82/020 or NYSDOH-ELAP item 198.1 and/or 198.6 was used to analyze all samples. Matrix interference and/or resolution limits (i.e. detecting asbestos in non-friable organically bound materials) may yield false results in certain circumstances. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing. Interpretation and use of test results are the responsibility of the client. ETL, Inc. is not responsible for the accuracy of the results when requested to physically separate and analyze layered samples. Any PLM results below 10% should be re-analyzed using the EPA recommended Point Count method. Any material that has greater than 1% asbestos content is considered to be an Asbestos Containing Material (ACM). These materials are regulated by both OSHA and the EPA and must be treated accordingly. Results are related to only to samples that were tested.

Asbestos Material Sampling Summary Sheet

Miscellaneous materials

Revision date 5/7/2015

Job #:	199858		Building:	943 McCullough St		Date:	12/22/17	
Material no.	Material Description	Friable (F)/ Non-Friable (NF)	Sample Letter	Sample Location	Material Located throughout bldg (Please List all Rooms)	Quantity	Picture #	
01	Material: Window glaze Description: white	NF	A	North window ext	ext window house	8 units	12	
02	Material: House wrap Description: tan	NF	B	East window ext	ext house	2432 SF	8	
03	Material: Shingle Description: grey	NF	A	East ext house	ext house	1008 SF	10,17	
04	Material: Felt paper Description: black	NF	B	South ext house	ext house	1008 SF	11	
05	Material: Window caulk Description: white	NF	A	North ext roof	ext house	8 units	12	
	Material: Description:		B	West ext roof	ext house			
	Material: Description:		A	Same as 03A	ext house			
	Material: Description:		B	Same as 03B	ext house			
	Material: Description:		A	Window south ext	ext house			
	Material: Description:		B	Window west ext	ext house			
	Material: Description:		A					
	Material: Description:		B					
	Material: Description:		A					
	Material: Description:		B					
	Material: Description:		A					
	Material: Description:		B					

**Bulk Asbestos
 Chain of Custody**

ETL Project #: 199858

Client: ETC	Contact: <u>Liv Hagerman</u>	Project Location/Name: <u>943 McCollough, Lansing MI</u>
Address: 721 N. Capitol Ave. Suite 3, Lansing, MI 48906	Phone: (734) 955-6600	Client Project #: <u>199858</u>
	Fax: (734) 955-6604	Date Sampled: <u>2/15/18</u>
	E-mail: <u>results@2etl.com</u>	
Please Provide Results: <input type="checkbox"/> Email <input type="checkbox"/> Fax <input type="checkbox"/> Verbal <input type="checkbox"/> Other _____		

Turnaround Time (TAT): RUSH Same Day 24 hr 48 hr Standard (3+ days) Other _____

PLM Instructions
 (Check all that apply) 3 days

<input checked="" type="checkbox"/> PLM EPA600/R-93/116, 1993 (Standard method)	<input checked="" type="checkbox"/> Stop at 1st Positive - Clearly mark Homogenous Group
<input type="checkbox"/> Point Counting: 400 Points*	
<input type="checkbox"/> PLM Non-Building Material (Dust, Wipe, Tape)	<input type="checkbox"/> Soil or Vermiculite Analysis *

* Additional charge and turnaround may be required

Lab ID	Sample ID	Sample Location	Material Description
	<u>06A-C</u>		
	<u>07A-E</u>		
	<u>08A-C</u>		
	<u>09A-B</u>		
	↓		
	<u>15A-B</u>		

	Date	Time
Relinquished (Name/Organization): <u>Take Gleason ETC Group</u>	<u>2/15/18</u>	<u>8:00</u> am/pm
Received (Name/ETL): <u>[Signature]</u>	<u>2/16/18</u>	<u>11:00</u> am/pm
Stereoscopy Analysis (Name/ETL): <u>David Garrison</u>	<u>2/16/18</u>	<u>2:00</u> am/pm
Sample Login (Name/ETL): <u>Brittany Wales</u>	<u>2/16/18</u>	<u>12:23</u> am/pm
Analysis (Name/ETL): <u>David Garrison</u>	<u>2/16/18</u>	<u>2:00</u> am/pm
QA/QC Review (Name/ETL): <u>Amia [Signature]</u>	<u>2.19.18</u>	<u>11:35</u> am/pm

Special Instructions:	Remarks:
------------------------------	-----------------

Asbestos Material Sampling Summary Sheet

Surfacing materials

Revision date 5/7/2015

Job #:	Building: 943 McCullough, Lansing			Date: 7/15/18	Material Located throughout bldg (Please List all Rooms)	Quantity	Picture #
Material no.	Material Description	Friable (F) / Non-Friable (NF)	Sample Letter	Sample Location			
6	Material: Stucco white textured ceiling	F	A	N ceiling rm 9	68-1009	144	
			B	S ceiling rm 9	610		
			C	middle ceiling rm 9	611 9		
7	Material: Plaster Blue grey	NF	A	rm 7 W wall	612	3500	
			B	rm 8 S wall	613		
			C	rm 9 E wall	614		
			D	rm 11 N wall	615		
			E	rm 13 N wall	616		
	Material:						

<1000 SF = 3 samples

1000 - <5000 = 5 samples

Asbestos Material Sampling Summary Sheet TSI (Thermal System Insulation) materials

Revision date 5/7/2015

Job #:	Building: 943 McCollough Lansing		Date:	Material Located throughout bldg (Please List all Rooms)	Quantity	Picture #
Material no.	Material Description	Friable (F) / Non-Friable (NF)	Sample Letter	Sample Location		
8	Material: Duct wrap Description: Brown	F	A	RM 8 vent 687617	325	
	Material: Description		B	RM 13 vent 618		
	Material: Description		C	RM 3 vent 619		
	Material: Description					
	Material: Description					
	Material: Description					
	Material: Description					
	Material: Description					
	Material: Description					
	Material: Description					
	Material: Description					
	Material: Description					

3 samples with the exception of patches less than 6 LF or 6 SF, then only 1 sample

Asbestos Material Sampling Summary Sheet
Miscellaneous materials

Revision date 5/7/2015

Job #:	199858		Building:	943 McLaughlin		Date:	2/5/18	
Material no.	Material Description	Friable (F) / Non-Friable (NF)	Sample Letter	Sample Location	Material Located throughout bldg (Please List all Rooms)	Quantity	Picture #	
9	Material: Blown-in-insulation Description: grey	F	A	rm 8 S wall 60876020	throughout	5900		
	Material: Dry wall Description: white	F	B	rm 7 W wall 6021				
10	Material: mud Description: white	F	A	rm 3 W wall 6022	1-6/12	3900		
	Material: tape Description: white	F	B	rm 5 S wall 6023				
11	Material: mastic (under 8) Description: yellow	NF	A	rm 3 W wall 6024	1-6/12	3900		
	Material: paired concrete Description: grey	NF	B	rm 5 S wall 6025				
12	Material: 12x12 tile Description: white	F	A	rm 3 W wall 6026	1-6/12	3900		
	Material: mastic (under 8) Description: yellow	NF	B	rm 5 S wall 6027				
13	Material: mastic (under 8) Description: yellow	NF	A	rm 6 entry 6028	6	54		
	Material: paired concrete Description: grey	NF	B	rm 6 N wall 6029				
14	Material: mastic (under 8) Description: yellow	NF	A	rm 6 entry 6030	6	54		
	Material: paired concrete Description: grey	NF	B	rm 6 N wall 6031				
15	Material: mastic (under 8) Description: yellow	NF	A	rm 14 middle 6032	14/15	6205		
	Material: paired concrete Description: grey	NF	B	rm 15 middle 6033				
	Material: mastic (under 8) Description: yellow		A					
	Material: paired concrete Description: grey		B					
	Material: mastic (under 8) Description: yellow		A					
	Material: paired concrete Description: grey		B					

Attachment:

Inspection Procedures

Pre-Demolition Environmental Inspection Procedures

HAZARDOUS MATERIALS INSPECTION

A table showing hazardous materials, above the household quantity limitations, found at the house is included as **Table 1: Hazardous Materials**. This table lists non-asbestos materials that may be hazardous and require special handling and disposal requirements. Items that might be in this category include: mercury switches, fluorescent lighting tubes and ballasts, halogen lights, Freon in refrigeration units, pesticides, herbicides, paints, solvents, etc.

Under the Resource Conservation and Recovery Act (RCRA) that addresses hazardous wastes, there is a residential household quantity exclusion. Materials are listed in Table I if they are present in quantities larger than what would typically be expected to be used and disposed in a normal household, and/or may require special handling and disposal requirements, such as: paints, solvents, adhesives, oils, tires, large circuit boards (such as televisions, computers, and security systems), prescription drugs, and syringes. On the other hand, if there were only household sized containers of maintenance, cleaning, non-prescription health and personal hygiene products, radios, and controllers present, as would be found in most homes, these materials would not be listed.

Fluorescent lighting systems have ballasts that have the potential to contain polychlorinated biphenyls (PCBs). Although PCBs are no longer commercially produced in the United States, they may be present in U.S. products that were produced prior to 1979, and may still be commercially available from other countries. Fluorescent bulbs, thermostats, and thermometers may contain mercury and can be treated as Universal Waste, which are streamlined standards for managing common types of hazardous waste.

If obtained, photographs of hazardous materials for the above referenced property are included in **Attachment: Site Photographs**.

ASBESTOS CONTAINING BUILDING MATERIAL INSPECTION

The property was inspected for the presence of asbestos-containing materials (ACMs) in order to meet the requirements of 40 CFR, Part 61, Subpart M, National Emissions Standards for Hazardous Air Pollutants (NESHAP).

Asbestos Inspection

The property was inspected for the presence of suspected ACMs. Typical building materials that may contain asbestos included drywall, plaster, stucco, floor tiles, roofing felt and shingles, ceiling tiles, insulation, pipe insulation, and duct insulation.

Sample Collection

Representative bulk samples of suspect asbestos containing building materials were randomly collected within each building area. The materials sampled were broken down into distinct homogenous (similar) materials. Homogenous material determination was based on the following criteria:

- Similar physical characteristics (same color and texture, etc.)
- Application (sprayed-on, troweled-on, assembly into a system etc.)
- Material function (Thermal insulation, floor tile, wallboard system etc.)

Pre-Demolition Environmental Inspection Procedures

At least two samples of each suspected asbestos containing material identified during the inspection was collected. For surfacing materials (sprayed and/or troweled on) a minimum of three samples were collected for areas that contained less than 1000 square feet of the material; 5 samples were collected for materials 1000 to 5000 square feet, and 7 samples were taken for areas greater than 5000 square feet. A Michigan Accredited Asbestos Inspector collected representative samples of each suspected ACM. Each sample was placed into a sealed plastic bag and labeled. A description of the material and location of the sample collected was recorded in the field notes. The total quantity of each suspected ACM was estimated and recorded in the field notes.

A listing of suspect ACMs at this property that were sampled and sent to the laboratory for analysis is included in **Table 2**. A copy of a floor plan showing sample locations is included in **Attachment: Site Drawing**.

Laboratory Analysis / Results

Each sample of suspect ACM collected at this property was analyzed for asbestos content using polarized light microscopy (PLM) by a NVLAP and NIST accredited laboratory in accordance with 40 CFR Ch. I (1-1-87 Edition) Part 763, Subpart F, Appendix A, pp. 293-299. Asbestos containing materials are defined as materials that contain greater than one percent (>1%) asbestos.

Each sample collected for analysis was delivered to either IATL (International Asbestos Testing Laboratories), 9000 Commerce Parkway, Suite B, Mt. Laurel, NJ 08054, ETL (Environmental Testing Laboratories), 38900 W. Huron River Drive, Suite 200, Romulus, MI 48174, and/or ACM Engineering & Environmental Services, 26598 US Highway 20 West, South Bend, IN 46628. Laboratory results are included in **Attachment: Laboratory Analytical Results**.

SIGNATURE

This report was prepared based on the site conditions that existed at the time of the inspection, sample collection, and the laboratory analytical results.

Prepared by:  

Heather Davis & Jake Gleason, Michigan Certified Asbestos Inspector (s)
Michigan Accreditation Number (s) A-48908 & A-49991

PRE-DEMOLITION ENVIRONMENTAL INSPECTION SUMMARY REPORT

Prepared For:

Ingham County Land Bank
3024 Turner Street
Lansing, MI 48906

Parcel:	33-01-01-22-206-161
House No:	1036 Dakin St, Lansing, MI 48912
Date Inspected:	12/3/2017
Inspected By:	Jake Gleason
Inspectors State Card #	A-49991

Building Information

No. Stories	1	Garage	No Garage
Square Footage	1000 SF	Garage Square Footage	NA
Basement Square Footage	900 SF	Garage Siding	NA
Siding	Aluminum	Garage Color	NA
Color	White	Garage Shingles	NA
Roof Shingles	Asphalt	Electric (Gone)	Disconnected
Asbestos present	YES	Gas (Gone)	Disconnected
Inaccessible areas			



Pre-Demolition Environmental Inspection Summary Report

Parcel: 33-01-01-22-206-161
House No. 1036 Dakin St, Lansing, MI 48912
Date Inspected: 12/3/2017

TABLE 1

HAZARDOUS MATERIALS

Material Description	Quantity & Units	Location
Hot Water Heater	1	Room 9
Refrigerator	1	Room 7
Light Ballast	Multiple	Room 2, 3, 7
Smoke Detector	1	Room 2
Florescent Light Bulbs	Multiple	Room 2, 3, 7

TIRE(s) REPORT

Material **Quantity & Units** **Location**

None observed above household quantities

Pre-Demolition Environmental Inspection Summary Report

Parcel: 33-01-01-22-206-161
 House No. 1036 Dakin St, Lansing, MI 48912
 Date Inspected: 12/3/2017


TABLE 2
SUSPECT ASBESTOS CONTAINING MATERIALS


Material #	Friable (F) / Non-Friable (NF)	Material Description	Material Location	Estimated Quantity	ACM Present
1	F	Plaster, white	Throughout	2900 SF	YES
2	F	Textured ceiling, white	Room 1, 2, 3	450 SF	No
3	F	Duct wrap, brown/black	Throughout	20 LF	YES
4	F	Ceiling tile, white bumpy	Room 6	144 SF	No
5	F	Ceiling tile, white smooth	Room 4	144 SF	No
6	NF	Linoleum, brown and yellow	Room 4	144 SF	YES
7	NF	12x12 Peel and stick, yellow	Room 3, 5	60 SF	No
8	NF	Linoleum, flower yellow	Room 6	144 SF	YES
9	NF	12x12 Peel and stick, diamond yellow	Room 7	96 SF	YES
10	NF	9x9 Tile, red and tan	Room 7	96 SF	YES
11	F	Mastic, black (under 10)	Room 7	96 SF	No
12	NF	Poured cement, grey	Room 8	800 SF	No
13	NF	House wrap, brown	Exterior	1800 SF	No
14	F	Window glaze, white	Exterior	14 windows	YES
15	F	Asphalt shingle, black	Exterior (house)	1500 SF	No
16	F	Asphalt shingle, white	Exterior (shed)	50 SF	No
17	NF	Blown-in-insulation, grey	Throughout	1000 SF	No

Table 2 - Is a summary of the materials that were sampled. Materials that test positive for asbestos have been bolded to make identification easier. Quantities that are listed are estimates only. It is the contractor's responsibility to verify all amounts of asbestos identified during the bid process.

Attachment:

Site Drawing




 Sample Location



Please Note: This is a rough floor plan only. All items, (doorways, Windows, etc.) may not be included in this illustration. Also, room and component sizes are not drawn to scale.

Basement

33-01-01-22-206-161
1036 Dakin St, Lansing, MI 48912
12/3/2017



Attic



 Sample Location

Please Note: This is a rough floor plan only. All items, (doorways, Windows, etc.) may not be included in this illustration. Also, room and component sizes are not drawn to scale.

Attachment:

Site Photographs

Representative Pictures of House/Property

Parcel: 33-01-01-22-206-161
House No. 1036 Dakin St, Lansing, MI 48912
Date Inspected: 12/3/2017



Front of house/property



Side #1 of house/property



Back of house/property



Side #2 of house/property

Representative Pictures of House/Property

Parcel: 33-01-01-22-206-161
House No. 1036 Dakin St, Lansing, MI 48912
Date Inspected: 12/3/2017



Shed



Shed 2

Representative Pictures of Hazardous Materials

Parcel: 33-01-01-22-206-161
House No. 1036 Dakin St, Lansing, MI 48912
Date Inspected: 12/3/2017



Refrigerator



Smoke Detector

Representative Pictures of Asbestos Containing Materials

Parcel: 33-01-01-22-206-161
House No. 1036 Dakin St, Lansing, MI 48912
Date Inspected: 12/3/2017



Plaster



Duct wrap



Linoleum, brown/yellow



Linoleum, flower yellow

Representative Pictures of Asbestos Containing Materials

Parcel: 33-01-01-22-206-161
House No. 1036 Dakin St, Lansing, MI 48912
Date Inspected: 12/3/2017



12x12 Peel and Stick, yellow; 9x9 Floor tile, red/tan



Window glaze

Attachment:

Laboratory Analytical Results

ENVIRONMENTAL TESTING LABORATORIES, INC.



38900 HURON RIVER DRIVE, SUITE 200
ROMULUS, MICHIGAN 48174
(734) 955-6600
FAX: (734) 955-6604

To : Environmental Testing And Consulting Inc.
38900 Huron River Drive
Romulus, MI 48174

Project Location :
1036 Dakin St, Lansing, MI

Attention :

Client Project : 33-01-01-22-206-161

ETC Job : 199857

Report Date : 12/7/2017

Login #	Sample ID	Work Requested	Completed
634795	01A	Asbestos Analysis	12/07/2017
634796	01B	Asbestos Analysis	12/07/2017
634797	01C	Asbestos Analysis	12/07/2017
634798	01D	Asbestos Analysis	12/07/2017
634799	01E	Asbestos Analysis	12/07/2017
634800	02A	Asbestos Analysis	12/07/2017
634801	02B	Asbestos Analysis	12/07/2017
634802	02C	Asbestos Analysis	12/07/2017
634803	03A	Asbestos Analysis	12/07/2017
634804	03B	Asbestos Analysis	12/07/2017
634805	03C	Asbestos Analysis	12/07/2017
634806	04A	Asbestos Analysis	12/07/2017
634807	04B	Asbestos Analysis	12/07/2017
634808	05A	Asbestos Analysis	12/07/2017
634809	05B	Asbestos Analysis	12/07/2017
634810	06A	Asbestos Analysis	12/07/2017
634811	06B	Asbestos Analysis	12/07/2017
634812	07A	Asbestos Analysis	12/07/2017
634813	07B	Asbestos Analysis	12/07/2017
634814	08A	Asbestos Analysis	12/07/2017

This report is intended for use solely by the individual or entity to which it is addressed. This report may not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government. It may contain information that is privileged, confidential and otherwise exempt by law from disclosure. If the reader of this information is not the intended recipient or an employee of its intended recipient, you are herewith notified that any dissemination, distribution or copying of this information is strictly prohibited. If you have received this information in error, please notify ETL immediately. Thank you.

Login #	Sample ID	Work Requested	Completed
634815	08B	Asbestos Analysis	12/07/2017
634816	09A	Asbestos Analysis	12/07/2017
634817	09B	Asbestos Analysis	12/07/2017
634818	10A	Asbestos Analysis	12/07/2017
634819	10B	Asbestos Analysis	12/07/2017
634820	11A	Asbestos Analysis	12/07/2017
634821	11B	Asbestos Analysis	12/07/2017
634822	12A	Asbestos Analysis	12/07/2017
634823	12B	Asbestos Analysis	12/07/2017
634824	13A	Asbestos Analysis	12/07/2017
634825	13B	Asbestos Analysis	12/07/2017
634826	14A	Asbestos Analysis	12/07/2017
634827	14B	Asbestos Analysis	12/07/2017
634828	15A	Asbestos Analysis	12/07/2017
634829	15B	Asbestos Analysis	12/07/2017
634830	16A	Asbestos Analysis	12/07/2017
634831	16B	Asbestos Analysis	12/07/2017
634832	17A	Asbestos Analysis	12/07/2017
634833	17B	Asbestos Analysis	12/07/2017

Reviewed by:



Quality Assurance Coordinator

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
 38900 Huron River Drive
 Romulus, MI 48174

Location :
 1036 Dakin St, Lansing, MI

ETC Job : 199857
Client Project : 33-01-01-22-206-161
Date Collected : 12/03/2017
Date Received : 12/05/2017
Date Analyzed : 12/07/2017

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
634795 01A ceiling middle rm 1 Analyst: Daniel Agnew	Plaster	White Non-Fibrous Homogenous	1.25% Cellulose	98.25% Other	PC 0.5% Chrysotile
634796 01B E wall sentry rm 2 Layer-1 Analyst: Daniel Agnew	Plaster	White Non-Fibrous Homogenous	0.75% Cellulose	98.5% Other	PC 0.75% Chrysotile
634796 01B E wall sentry rm 2 Layer-2 Analyst: Daniel Agnew	Texture	White Non-Fibrous Homogenous		100% Other	None Detected
634797 01C E wall N entry rm 2 Analyst: Daniel Agnew	Texture	White Non-Fibrous Homogenous	0.75% Cellulose	98% Other	PC 1.25% Chrysotile
634798 01D N wall 5 Layer-1 Analyst: Daniel Agnew	Plaster	White Non-Fibrous Homogenous	1.25% Cellulose	98.25% Other	PC 0.5% Chrysotile
634798 01D N wall 5 Layer-2 Analyst: Daniel Agnew	Texture	White Non-Fibrous Homogenous		100% Other	None Detected
634799 01E E wall rm 7 Analyst: Daniel Agnew	Plaster	White Non-Fibrous Homogenous		98.5% Other	PC 1.5% Chrysotile

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
38900 Huron River Drive
Romulus, MI 48174

Location :
1036 Dakin St, Lansing, MI

ETC Job : 199857
Client Project : 33-01-01-22-206-161
Date Collected : 12/03/2017
Date Received : 12/05/2017
Date Analyzed : 12/07/2017

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
634800 02A center rm 2 Analyst: Daniel Agnew	Textured Ceiling	White Non-Fibrous Homogenous		100% Other	None Detected
634801 02B center rm 1 Analyst: Daniel Agnew	Textured Ceiling	White Non-Fibrous Homogenous	1% Cellulose	99% Other	None Detected
634802 02C center rm 3 Analyst: Daniel Agnew	Textured Ceiling	White Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
634803 03A rm 5 vent Analyst: Daniel Agnew	Duct Wrap	Black/Brown Fibrous Homogenous	25% Cellulose	5% Other	70% Chrysotile
634804 03B rm 1 W vent Analyst: Daniel Agnew	Duct Wrap	Black/Brown Fibrous Homogenous	20% Cellulose	15% Other	65% Chrysotile
634805 03C rm 6 e vent Analyst: Daniel Agnew	Duct Wrap	Black/Brown Fibrous Homogenous	20% Cellulose	10% Other	70% Chrysotile
634806 04A rm 6 W side Analyst: Daniel Agnew	Ceiling Tile	White Fibrous Homogenous	100% Cellulose		None Detected

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
 38900 Huron River Drive
 Romulus, MI 48174

Location :
 1036 Dakin St, Lansing, MI

ETC Job : 199857
Client Project : 33-01-01-22-206-161
Date Collected : 12/03/2017
Date Received : 12/05/2017
Date Analyzed : 12/07/2017

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
634807 04B rm 6 middle Analyst: Daniel Agnew	Ceiling Tile	White Fibrous Homogenous	100% Cellulose		None Detected
634808 05A rm 4 E side Analyst: Daniel Agnew	Ceiling Tile	White Fibrous Homogenous	100% Cellulose		None Detected
634809 05B rm 4 middle Analyst: Daniel Agnew	Ceiling Tile	White Fibrous Homogenous	97% Cellulose	3% Other	None Detected
634810 06A rm 4 entry Analyst: Daniel Agnew	Linoleum	Brown/Yellow Fibrous Homogenous	15% Cellulose	35% Other	50% Chrysotile
634811 06B rm 4 middle Analyst: Daniel Agnew	Linoleum	Brown/Yellow Fibrous Homogenous	10% Cellulose	40% Other	50% Chrysotile
634812 07A rm 3 E entry Analyst: Daniel Agnew	12x12 Peel & Stick	Yellow Non-Fibrous Homogenous		100% Other	None Detected
634813 07B rm 5 s entry Analyst: Daniel Agnew	12x12 Peel & Stick	Yellow Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
 38900 Huron River Drive
 Romulus, MI 48174

Location :
 1036 Dakin St, Lansing, MI

ETC Job : 199857
Client Project : 33-01-01-22-206-161
Date Collected : 12/03/2017
Date Received : 12/05/2017
Date Analyzed : 12/07/2017

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
634814 08A rm 6 entry Analyst: Daniel Agnew	Linoleum	Grey Fibrous Homogenous	34% Cellulose	31% Other	35% Chrysotile
634815 08B rm 6 middle Analyst: Daniel Agnew	Linoleum	Grey Fibrous Homogenous	30% Cellulose	25% Other	45% Chrysotile
634816 09A rm 7 E entry Analyst: Daniel Agnew	12x12 Peel & Stick	Yellow Non-Fibrous Homogenous	2% Cellulose	96% Other	2% Chrysotile
634817 09B rm 7 w entry Analyst: Daniel Agnew	12x12 Peel & Stick	Yellow Non-Fibrous Homogenous	2% Cellulose	96% Other	2% Chrysotile
634818 10A rm 7 E entry Analyst: Daniel Agnew	9x9 Floor Tile	Red/Tan Non-Fibrous Homogenous	1% Cellulose	97% Other	2% Chrysotile
634819 10B rm 7 W entry Analyst: Daniel Agnew	9x9 Floor Tile	Red/Tan Non-Fibrous Homogenous	2% Cellulose	96% Other	2% Chrysotile
634820 11A rm 7 E entry Analyst: Daniel Agnew	Mastic	Black Non-Fibrous Homogenous	5% Cellulose	95% Other	None Detected

ETL, Inc. maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced without written approval by ETL, Inc. Test Method EPA 600/R-93-116 & EPA 600/M4-82/020 or NYSDOH-ELAP item 198.1 and/or 198.6 was used to analyze all samples. Matrix interference and/or resolution limits (i.e. detecting asbestos in non-friable organically bound materials) may yield false results in certain circumstances. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing. Interpretation and use of test results are the responsibility of the client. ETL, Inc. is not responsible for the accuracy of the results when requested to physically separate and analyze layered samples. Any PLM results below 10% should be re-analyzed using the EPA recommended Point Count method. Any material that has greater than 1% asbestos content is considered to be an Asbestos Containing Material (ACM). These materials are regulated by both OSHA and the EPA and must be treated accordingly. Results are related to only to samples that were tested.



Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
38900 Huron River Drive
Romulus, MI 48174

Location :
1036 Dakin St, Lansing, MI

ETC Job : 199857

Client Project : 33-01-01-22-206-161

Date Collected : 12/03/2017

Date Received : 12/05/2017

Date Analyzed : 12/07/2017

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
634821 11B rm 7 W entry Analyst: Daniel Agnew	Mastic	Black Non-Fibrous Homogenous	4% Cellulose	96% Other	None Detected
634822 12A rm 9 center Analyst: Daniel Agnew	Poured Cement	Grey Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
634823 12B rm 9 N center Analyst: Daniel Agnew	Poured Cement	Grey Non-Fibrous Homogenous	3% Cellulose	97% Other	None Detected
634824 13A NW corner Analyst: Daniel Agnew	House Wrap	Brown Fibrous Homogenous	100% Cellulose		None Detected
634825 13B NW corner Analyst: Daniel Agnew	House Wrap	Brown Fibrous Homogenous	100% Cellulose		None Detected
634826 14A rm 1 ext window Analyst: Daniel Agnew	Window Glaze	White Non-Fibrous Homogenous	3% Cellulose	95% Other	2% Chrysotile
634827 14B rm 4 ext window Analyst: Daniel Agnew	Window Glaze	White Non-Fibrous Homogenous	3% Cellulose	94% Other	3% Chrysotile

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
 38900 Huron River Drive
 Romulus, MI 48174

Location :
 1036 Dakin St, Lansing, MI

ETC Job : 199857
 Client Project : 33-01-01-22-206-161
 Date Collected : 12/03/2017
 Date Received : 12/05/2017
 Date Analyzed : 12/07/2017

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
634828 15A middle E side Analyst: Daniel Agnew	Asphalt Shingle	Black Non-Fibrous Homogenous	7% Cellulose	93% Other	None Detected
634829 15B back porch Analyst: Daniel Agnew	Asphalt Shingle	Black Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
634830 16A NW corner Analyst: Daniel Agnew	Asphalt Shingle	White Non-Fibrous Homogenous	10% Cellulose	90% Other	None Detected
634831 16B SE corner Analyst: Daniel Agnew	Asphalt Shingle	White Non-Fibrous Homogenous	8% Cellulose	92% Other	None Detected
634832 17A N side Analyst: Daniel Agnew	Blown Insulation	Brown Fibrous Homogenous	1% Cellulose 98% Fiberglass	1% Other	None Detected
634833 17B S side Analyst: Daniel Agnew	Blown Insulation	Brown Fibrous Homogenous	99% Fiberglass	1% Other	None Detected



Lab Supervisor/Other Signatory



Analyst: Daniel Agnew



Certificate of Analysis

Environmental Testing Laboratories, Inc.
38900 Huron River Drive,
Suite 200, Romulus, Michigan 48174,
(734) 955-6600, Fax: (734) 955-6604

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
38900 Huron River Drive
Romulus,MI 48174

Location :
1036 Dakin St, Lansing, MI

ETC Job : 199857
Client Project : 33-01-01-22-206-161
Date Collected : 12/03/2017
Date Received : 12/05/2017
Date Analyzed : 12/07/2017

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
--------	-------------	------------	-----------	---------------	------------

400 Point Count Results by EPA 600/R-93/116 PLM (denoted by "PC")
Item 198.1: PLM Methods for Identifying and Quantitating Asbestos in Bulk Samples
Item 198.6: PLM Methods for Identifying and Quantitating Asbestos in Non-Friable Organically Bound Bulk Samples
EPA 600/R-93/116: Method for Determination of Asbestos in Bulk Building Materials
EPA 600/M4-82-020: Interim Method for Determination of Asbestos in Bulk Insulation Samples

ETL, Inc. maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced without written approval by ETL, Inc. Test Method EPA 600/R-93-116 & EPA 600/M4-82/020 or NYSDOH-ELAP item 198.1 and/or 198.6 was used to analyze all samples. Matrix interference and/or resolution limits (i.e. detecting asbestos in non-friable organically bound materials) may yield false results in certain circumstances. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing. Interpretation and use of test results are the responsibility of the client. ETL, Inc. is not responsible for the accuracy of the results when requested to physically separate and analyze layered samples. Any PLM results below 10% should be re-analyzed using the EPA recommended Point Count method. Any material that has greater than 1% asbestos content is considered to be an Asbestos Containing Material (ACM). These materials are regulated by both OSHA and the EPA and must be treated accordingly. Results are related to only to samples that were tested.

**Bulk Asbestos
 Chain of Custody**

ETL Project #: 199857

Client: ETC	Contact: <u>Liv Hagerman</u>	Project Location/Name: <u>1036 DAWSON ST</u> <u>LANSING MI</u>
Address: 721 N. Capitol Ave. Suite 3, Lansing, MI 48906	Phone: (734) 955-6600 Fax: (734) 955-6604 E-mail: <u>results@2etil.com</u>	Client Project #: <u>199857</u> Date Sampled: <u>12/3/17</u>
Please Provide Results: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Fax <input type="checkbox"/> Verbal <input type="checkbox"/> Other		

Turnaround Time (TAT): RUSH Same Day 24 hr 48 hr Standard (3+ days) Other

PLM Instructions
(Check all that apply)

<input type="checkbox"/> PLM EPA600/R-93/116, 1993 (Standard method)	<input type="checkbox"/> Stop at 1st Positive - Clearly mark Homogenous Group
<input type="checkbox"/> Point Counting: 400 Points*	
<input type="checkbox"/> PLM Non-Building Material (Dust, Wipe, Tape)	<input type="checkbox"/> Soil or Vermiculite Analysis *

* Additional charge and turnaround may be required

Lab ID	Sample ID	Sample Location	Material Description
634795	01 ABCDE		
↓	02 ABC	Please see Attached Sheets	
	03 ABC		
	04 AB		
634833	17 AB		

	Date	Time
Relinquished (Name/Organization): <u>Jake Gleason</u>	<u>12/3/17</u>	<u>5:00 pm</u>
Received (Name/ETL): <u>[Signature]</u>	<u>12.5.17</u>	<u>am/pm</u>
Stereoscopic Analysis (Name/ETL): <u>[Signature]</u>	<u>12-6-17</u>	<u>am/pm</u>
Sample Login (Name/ETL): <u>[Signature]</u>	<u>12.5.17</u>	<u>am/pm</u>
Analysis (Name/ETL): <u>[Signature]</u>	<u>12-6-17</u>	<u>am/pm</u>
QA/QC Review (Name/ETL): <u>[Signature]</u>	<u>12/17/17</u>	<u>am/pm</u>
Special Instructions:	Remarks	

Asbestos Material Sampling Summary Sheet

Surfacing materials

Revision date 5/7/2015

Job #: 199857		Building: 1036 DAKW ST, Cansby MI			Date: 12/3/17		
Material no.	Material Description	Friable (F) / Non-Friable (NF)	Sample Letter	Sample Location	Material Located throughout bldg (Please List all Rooms)	Quantity	Picture #
1	Material: Plaster	F	A	ceiling middle rm 163	795	throughout	2000
	white		B	e wall entry rm 2	796		
			C	e wall 12 entry rm 2	797		
			D	N wall 5	798		
			E	e wall rm 7	799		
2	Material: textured ceiling	F	A	center rm 2	800	4, 2, 3	450
	white		B	center rm 1	801		
			C	center rm 3	802		
	Material:						

<1000 SF = 3 samples

1000 - <5000 = 5 samples

265

Asbestos Material Sampling Summary Sheet

TSI (Thermal System Insulation) materials

Revision date 5/7/2015

Job #: 190857		Building: 1036 Dakin St, Lansing MI			Date: 12/3/17		
Material no.	Material Description	Friable (F) / Non-Friable (NF)	Sample Letter	Sample Location	Material Located throughout bldg (Please List all Rooms)	Quantity	Picture #
3	Material: Duct wrap	F	A	rm 5 vent 634803	throughout	20	
	Description: brown/black		B	rm 1 w vent 804			
			C	rm 6 e vent 805			
	Material: Description:						
	Material: Description:						
	Material: Description:						
	Material: Description:						
	Material: Description:						
	Material: Description:						
	Material: Description:						

3 samples with the exception of patches less than 6 LF or 6 SF, then only 1 sample

Asbestos Material Sampling Summary Sheet

Miscellaneous materials

Revision date 5/7/2015

Job #: 190857		Building: 1036 DAKIN ST, Lansing			Date: 12/3/17		
Material no.	Material Description	Friable (F) / Non-Friable (NF)	Sample Letter	Sample Location	Material Located throughout bldg (Please List all Rooms)	Quantity	Picture #
4	Material: ceiling tile	f	A	rm 6 east side 806	6	144	
	Description: white bumpy		B	rm 6 middle 807			
5	Material: ceiling tile	f	A	rm 4 E Side 808	4	144	
	Description: white smooth		B	rm 4 middle 809			
6	Material: linoleum	NF	A	rm 4 entry 810	4	144	
	Description: brown yellow		B	rm 4 middle 811			
7	Material: 12x12 P+S	NF	A	rm 3 e entry 812	3i 5	600	
	Description: yellow		B	rm 5 S entry 813			
8	Material: linoleum	NF	A	rm 6 entry 814	6	144	
	Description: flower yellow		B	rm 6 middle 815			
9	Material: 12x12 P+S	NF	A	rm 7 e entry 816	7	96	
	Description: diamond yellow		B	rm 7 w entry 817			
10	Material: 9x9 tile	NF	A	rm 7 e entry 818	7	96	
	Description: red + tan		B	rm 7 w entry 819			
11	Material: mastic (under 10)	f	A	rm 7 e entry 820	7	96	
	Description: black		B	rm 7 w entry 821			
12	Material: poured cement	NF	A	rm 9 center 822	8	800	
	Description: grey		B	rm 9 n center 823			
13	Material: house wrap	NF	A	NW corner 824	ext	1400	
	Description: brown		B	NW corner 825			

Asbestos Material Sampling Summary Sheet Miscellaneous materials

Revision date 5/7/2015

Job #:		Building: 1636 DAKIN ST, Lansing MI			Date: 12/3/17		
Material no.	Material Description	Friable (F) / Non-Friable (NF)	Sample Letter	Sample Location	Material Located throughout bldg (Please List all Rooms)	Quantity	Picture #
14	Material: window glaze Description: white	F	A	rm 1 ext window ⁶³⁴ 826	Ext	14	
			B	rm 4 ext window ⁸²⁷			
15	Material: Asphalt shingle Description: black	F	A	middle e side 828	ext house	1500	
			B	back porch 829			
16	Material: Asphalt shingle Description: white	F	A	NW corner 830	ext shed	500	
			B	SE corner 831			
17	Material: Blown in insulation Description: grey	NF	A	N side 832	through out	1000	
			B	S side 833			
	Material: Description:		A				
	Material: Description:		B				
	Material: Description:		A				
	Material: Description:		B				
	Material: Description:		A				
	Material: Description:		B				
	Material: Description:		A				
	Material: Description:		B				

2 samples

Sofr

Attachment:

Inspection Procedures

Pre-Demolition Environmental Inspection Procedures

HAZARDOUS MATERIALS INSPECTION

A table showing hazardous materials, above the household quantity limitations, found at the house is included as **Table 1: Hazardous Materials**. This table lists non-asbestos materials that may be hazardous and require special handling and disposal requirements. Items that might be in this category include: mercury switches, fluorescent lighting tubes and ballasts, halogen lights, Freon in refrigeration units, pesticides, herbicides, paints, solvents, etc.

Under the Resource Conservation and Recovery Act (RCRA) that addresses hazardous wastes, there is a residential household quantity exclusion. Materials are listed in Table I if they are present in quantities larger than what would typically be expected to be used and disposed in a normal household, and/or may require special handling and disposal requirements, such as: paints, solvents, adhesives, oils, tires, large circuit boards (such as televisions, computers, and security systems), prescription drugs, and syringes. On the other hand, if there were only household sized containers of maintenance, cleaning, non-prescription health and personal hygiene products, radios, and controllers present, as would be found in most homes, these materials would not be listed.

Fluorescent lighting systems have ballasts that have the potential to contain polychlorinated biphenyls (PCBs). Although PCBs are no longer commercially produced in the United States, they may be present in U.S. products that were produced prior to 1979, and may still be commercially available from other countries. Fluorescent bulbs, thermostats, and thermometers may contain mercury and can be treated as Universal Waste, which are streamlined standards for managing common types of hazardous waste.

If obtained, photographs of hazardous materials for the above referenced property are included in **Attachment: Site Photographs**.

ASBESTOS CONTAINING BUILDING MATERIAL INSPECTION

The property was inspected for the presence of asbestos-containing materials (ACMs) in order to meet the requirements of 40 CFR, Part 61, Subpart M, National Emissions Standards for Hazardous Air Pollutants (NESHAP).

Asbestos Inspection

The property was inspected for the presence of suspected ACMs. Typical building materials that may contain asbestos included drywall, plaster, stucco, floor tiles, roofing felt and shingles, ceiling tiles, insulation, pipe insulation, and duct insulation.

Sample Collection

Representative bulk samples of suspect asbestos containing building materials were randomly collected within each building area. The materials sampled were broken down into distinct homogenous (similar) materials. Homogenous material determination was based on the following criteria:

- Similar physical characteristics (same color and texture, etc.)
- Application (sprayed-on, troweled-on, assembly into a system etc.)
- Material function (Thermal insulation, floor tile, wallboard system etc.)

Pre-Demolition Environmental Inspection Procedures

At least two samples of each suspected asbestos containing material identified during the inspection was collected. For surfacing materials (sprayed and/or troweled on) a minimum of three samples were collected for areas that contained less than 1000 square feet of the material; 5 samples were collected for materials 1000 to 5000 square feet, and 7 samples were taken for areas greater than 5000 square feet. A Michigan Accredited Asbestos Inspector collected representative samples of each suspected ACM. Each sample was placed into a sealed plastic bag and labeled. A description of the material and location of the sample collected was recorded in the field notes. The total quantity of each suspected ACM was estimated and recorded in the field notes.

A listing of suspect ACMs at this property that were sampled and sent to the laboratory for analysis is included in **Table 2**. A copy of a floor plan showing sample locations is included in **Attachment: Site Drawing**.


Laboratory Analysis / Results

Each sample of suspect ACM collected at this property was analyzed for asbestos content using polarized light microscopy (PLM) by a NVLAP and NIST accredited laboratory in accordance with 40 CFR Ch. I (1-1-87 Edition) Part 763, Subpart F, Appendix A, pp. 293-299. Asbestos containing materials are defined as materials that contain greater than one percent (>1%) asbestos.

Each sample collected for analysis was delivered to either IATL (International Asbestos Testing Laboratories), 9000 Commerce Parkway, Suite B, Mt. Laurel, NJ 08054, ETL (Environmental Testing Laboratories), 38900 W. Huron River Drive, Suite 200, Romulus, MI 48174, and/or ACM Engineering & Environmental Services, 26598 US Highway 20 West, South Bend, IN 46628. Laboratory results are included in **Attachment: Laboratory Analytical Results**.

SIGNATURE

This report was prepared based on the site conditions that existed at the time of the inspection, sample collection, and the laboratory analytical results.



Prepared by: _____

Jake Gleason, Michigan Certified Asbestos Inspector (s)

Michigan Accreditation Number (s) A-49991

PRE-DEMOLITION ENVIRONMENTAL INSPECTION SUMMARY REPORT

Prepared For:

Ingham County Land Bank
3024 Turner Street
Lansing, MI 48906

Parcel:	33-01-01-22-206-142
House No:	1042 Dakin St, Lansing, MI 48912
Date Inspected:	12/15/2017
Inspected By:	Wade Wiltse
Inspectors State Card #	A-51051

Building Information

No. Stories	2	Garage	No Garage
Square Footage	720 SF	Garage Square Footage	NA
Basement Square Footage	720 SF	Garage Siding	NA
Siding	Asphalt	Garage Color	NA
Color	Blue/green	Garage Shingles	NA
Roof Shingles	Asphalt	Electric (Gone)	Disconnected
Asbestos present	YES	Gas (Gone)	Disconnected
Inaccessible areas			



Pre-Demolition Environmental Inspection Summary Report

Parcel: 33-01-01-22-206-142
House No. 1042 Dakin St, Lansing, MI 48912
Date Inspected: 12/15/2017

TABLE 1

HAZARDOUS MATERIALS

Material Description	Quantity & Units	Location
Hot Water Tank	7	Room 1
Air Conditioners/refrigerators/ freezers	13	Room 1, 7
Electronics	11	Room 7, 9
Fire Extinguishers	2	Room 4, 10
Misc. Items (solvents, cleaners)	10	Room 7
Thermostats	1	Room 1

TIRE(s) REPORT

Material **Quantity & Units** **Location**

None observed above household quantities

Pre-Demolition Environmental Inspection Summary Report

Parcel: 33-01-01-22-206-142
 House No. 1042 Dakin St, Lansing, MI 48912
 Date Inspected: 12/15/2017


TABLE 2
SUSPECT ASBESTOS CONTAINING MATERIALS

Material #	Friable (F) / Non-Friable (NF)	Material Description	Material Location	Estimated Quantity	ACM Present
1	NF	Plaster, grey	Throughout	2500 SF	No
2	F	Duct wrap, white	Room 10	2 SF	YES
3	NF	Drywall, white	Throughout	2500 SF	No
4	F	Tape, white	Throughout	23 SF	No
5	F	Mud, grey	Throughout	23 SF	No
6	NF	Flooring, tan	Room 1	540 SF	No
7	NF	Linoleum, grey	Room 3	144 SF	No
8	NF	12x12 Tile, tan	Room 3	144 SF	No
9	NF	Linoleum, grey	Room 4	180 SF	No
10	NF	Linoleum, brown	Room 4	180 SF	No
11	NF	Concrete block, grey	Rooms 7, 8, Exterior	528 SF	No
12	NF	Mortar, grey	Rooms 7, 8, Exterior	18 SF	No
13	NF	Poured cement, grey	Rooms 7, 8	720 SF	No
14	F	Blown-in-insulation, grey	Room 14	81 SF	No
15	NF	Linoleum, black	Room 5	54 SF	No
16	F	House wrap, tan	Exterior	1856 SF	No
17	NF	Shingle siding, black/green	Exterior	1856 SF	No
18	NF	Asphalt roof shingle, black	Exterior	720 SF	No

Table 2 - Is a summary of the materials that were sampled. Materials that test positive for asbestos have been bolded to make identification easier. Quantities that are listed are estimates only. It is the contractor's responsibility to verify all amounts of asbestos identified during the bid process.


Attachment:


Site Drawing



 Sample Location

Please Note: This is a rough floor plan only. All items, (doorways, Windows, etc.) may not be included in this illustration. Also, room and component sizes are not drawn to scale.




 Sample Location

Please Note: This is a rough floor plan only. All items, (doorways, Windows, etc.) may not be included in this illustration. Also, room and component sizes are not drawn to scale.

Basement

33-01-01-22-206-142
1042 Dakin St, Lansing, MI 48912
12/15/2017



 Sample Location

Please Note: This is a rough floor plan only. All items, (doorways, Windows, etc.) may not be included in this illustration. Also, room and component sizes are not drawn to scale.

Ingham County Land Bank
200410

Attachment:

Site Photographs

Representative Pictures of House/Property

Parcel: 33-01-01-22-206-142
House No. 1042 Dakin St, Lansing, MI 48912
Date Inspected: 12/15/2017



Front of house/property



Side #1 of house/property




Back of house/property



Side #2 of house/property

Representative Pictures of Hazardous Materials

Parcel: 33-01-01-22-206-142
House No. 1042 Dakin St, Lansing, MI 48912
Date Inspected: 12/15/2017




Hot Water Tank



Air Conditioners/refrigerators/freezers



Electronics



Fire Extinguishers

Representative Pictures of Hazardous Materials

Parcel: 33-01-01-22-206-142
House No. 1042 Dakin St, Lansing, MI 48912
Date Inspected: 12/15/2017



Misc. Items (solvents, cleaners)



Thermostats

Representative Pictures of Asbestos Containing Materials

Parcel:	33-01-01-22-206-142
House No.	1042 Dakin St, Lansing, MI 48912
Date Inspected:	12/15/2017



Duct Wrap

Attachment:

Laboratory Analytical Results

ENVIRONMENTAL TESTING LABORATORIES, INC.



38900 HURON RIVER DRIVE, SUITE 200
ROMULUS, MICHIGAN 48174
(734) 955-6600
FAX: (734) 955-6604

To : Environmental Testing And Consulting Inc.
38900 Huron River Drive
Romulus, MI 48174

Project Location :
1042 Dakin St, Lansing, MI 48912

Attention :

Client Project : N/A

ETC Job : 200410
Report Date : 12/20/2017

Login #	Sample ID	Work Requested	Completed
640801	01A	Asbestos Analysis	12/20/2017
640802	01B	Asbestos Analysis	12/20/2017
640803	01C	Asbestos Analysis	12/20/2017
640804	01D	Asbestos Analysis	12/20/2017
640805	01E	Asbestos Analysis	12/20/2017
640806	02A	Asbestos Analysis	12/20/2017
640807	02B	Asbestos Analysis	12/20/2017
640808	02C	Asbestos Analysis	12/20/2017
640809	03A	Asbestos Analysis	12/20/2017
640810	03B	Asbestos Analysis	12/20/2017
640811	04A	Asbestos Analysis	12/20/2017
640812	04B	Asbestos Analysis	12/20/2017
640813	05A	Asbestos Analysis	12/20/2017
640814	05B	Asbestos Analysis	12/20/2017
640815	06A	Asbestos Analysis	12/20/2017
640816	06B	Asbestos Analysis	12/20/2017
640817	07A	Asbestos Analysis	12/20/2017
640818	07B	Asbestos Analysis	12/20/2017
640819	08A	Asbestos Analysis	12/20/2017
640820	08B	Asbestos Analysis	12/20/2017

Login #	Sample ID	Work Requested	Completed
640821	09A	Asbestos Analysis	12/20/2017
640822	09B	Asbestos Analysis	12/20/2017
640823	10A	Asbestos Analysis	12/20/2017
640824	10B	Asbestos Analysis	12/20/2017
640825	11A	Asbestos Analysis	12/20/2017
640826	11B	Asbestos Analysis	12/20/2017
640827	12A	Asbestos Analysis	12/20/2017
640828	12B	Asbestos Analysis	12/20/2017
640829	13A	Asbestos Analysis	12/20/2017
640830	13B	Asbestos Analysis	12/20/2017
640831	14A	Asbestos Analysis	12/20/2017
640832	14B	Asbestos Analysis	12/20/2017
640833	15A	Asbestos Analysis	12/20/2017
640834	15B	Asbestos Analysis	12/20/2017
640835	16A	Asbestos Analysis	12/20/2017
640836	16B	Asbestos Analysis	12/20/2017
640837	17A	Asbestos Analysis	12/20/2017
640838	17B	Asbestos Analysis	12/20/2017
640839	18A	Asbestos Analysis	12/20/2017
640840	18B	Asbestos Analysis	12/20/2017

Reviewed by:



Quality Assurance Coordinator

Login #

Sample ID

Work Requested

Completed

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
 38900 Huron River Drive
 Romulus, MI 48174

Location :

1042 Dakin St, Lansing, MI 48912

ETC Job : 200410

Client Project : N/A

Date Collected : 12/15/2017

Date Received : 12/19/2017

Date Analyzed : 12/20/2017

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
640801 01A 1 N Wall Layer-2 Analyst: Liliane Mason	Plaster	Grey Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
640802 01B 5 W Wall Analyst: Liliane Mason	Plaster	Grey Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
640803 01C 2 E Wall Analyst: Liliane Mason	Plaster	Grey Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
640804 01D 9 W Wall Analyst: Liliane Mason	Plaster	Grey Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
640805 01E 11 W Wall Analyst: Liliane Mason	Plaster	Grey Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
640806 02A 10 E Wall Analyst: Liliane Mason	Duct Wrap	White Fibrous Homogenous		50% Other	50% Chrysotile
640807 02B 10 E Wall Analyst: Liliane Mason		Not Analyzed			

ETL, Inc. maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced without written approval by ETL, Inc. Test Method EPA 600/R-93-116 & EPA 600/M4-82/020 or NYSDOH-ELAP item 198.1 and/or 198.6 was used to analyze all samples. Matrix interference and/or resolution limits (i.e. detecting asbestos in non-friable organically bound materials) may yield false results in certain circumstances. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing. Interpretation and use of test results are the responsibility of the client. ETL, Inc. is not responsible for the accuracy of the results when requested to physically separate and analyze layered samples. Any PLM results below 10% should be re-analyzed using the EPA recommended Point Count method. Any material that has greater than 1% asbestos content is considered to be an Asbestos Containing Material (ACM). These materials are regulated by both OSHA and the EPA and must be treated accordingly. Results are related to only to samples that were tested.

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
 38900 Huron River Drive
 Romulus, MI 48174

Location :

1042 Dakin St, Lansing, MI 48912

ETC Job : 200410

Client Project : N/A

Date Collected : 12/15/2017

Date Received : 12/19/2017

Date Analyzed : 12/20/2017

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
640808 02C 10 E Wall Analyst: Liliane Mason		Not Analyzed			
640809 03A 1 E Wall Analyst: Liliane Mason	Drywall	White Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
640810 03B 2 E Wall Analyst: Liliane Mason	Drywall	White Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
640811 04A 1 E Wall Analyst: Liliane Mason	Tape	White Non-Fibrous Homogenous	80% Fiberglass	20% Other	None Detected
640812 04B 2 E Wall Analyst: Liliane Mason	Tape	White Non-Fibrous Homogenous	80% Cellulose	20% Other	None Detected
640813 05A 1 E Wall Analyst: Liliane Mason	Mud	Grey Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
640814 05B 2 E Wall Analyst: Liliane Mason	Mud	Grey Non-Fibrous Homogenous	1% Cellulose	99% Other	None Detected

ETL, Inc. maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced without written approval by ETL, Inc. Test Method EPA 600/R-93-116 & EPA 600/M4-82/020 or NYSDOH-ELAP item 198.1 and/or 198.6 was used to analyze all samples. Matrix interference and/or resolution limits (i.e. detecting asbestos in non-friable organically bound materials) may yield false results in certain circumstances. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing. Interpretation and use of test results are the responsibility of the client. ETL, Inc. is not responsible for the accuracy of the results when requested to physically separate and analyze layered samples. Any PLM results below 10% should be re-analyzed using the EPA recommended Point Count method. Any material that has greater than 1% asbestos content is considered to be an Asbestos Containing Material (ACM). These materials are regulated by both OSHA and the EPA and must be treated accordingly. Results are related to only to samples that were tested.

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
 38900 Huron River Drive
 Romulus, MI 48174

Location :

1042 Dakin St, Lansing, MI 48912

ETC Job : 200410

Client Project : N/A

Date Collected : 12/15/2017

Date Received : 12/19/2017

Date Analyzed : 12/20/2017

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
640815 06A 1 E Floor Analyst: Liliane Mason	Flooring	Tan Non-Fibrous Homogenous		99.25% Other	PC 0.75% Chrysotile
640816 06B 1 W Floor Analyst: Liliane Mason	Flooring	Tan Non-Fibrous Homogenous		99.5% Other	PC 0.5% Chrysotile
640817 07A 3 S Floor Analyst: Liliane Mason	Linoleum	Grey Non-Fibrous Homogenous	1% Cellulose	99% Other	None Detected
640818 07B 3 N Floor Analyst: Liliane Mason	Linoleum	Grey Non-Fibrous Homogenous	1% Cellulose	99% Other	None Detected
640819 08A 3 S Floor Analyst: Liliane Mason	12x12 Tile	Tan Non-Fibrous Homogenous	1% Cellulose	99% Other	None Detected
640820 08B 3 N Floor Analyst: Liliane Mason	12x12 Tile	Tan Non-Fibrous Homogenous	1% Cellulose	99% Other	None Detected
640821 09A 4 N Floor Analyst: Liliane Mason	Linoleum	Grey Fibrous Homogenous	20% Cellulose	80% Other	None Detected

ETL, Inc. maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced without written approval by ETL, Inc. Test Method EPA 600/R-93-116 & EPA 600/M4-82/020 or NYSDOH-ELAP item 198.1 and/or 198.6 was used to analyze all samples. Matrix interference and/or resolution limits (i.e. detecting asbestos in non-friable organically bound materials) may yield false results in certain circumstances. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing. Interpretation and use of test results are the responsibility of the client. ETL, Inc. is not responsible for the accuracy of the results when requested to physically separate and analyze layered samples. Any PLM results below 10% should be re-analyzed using the EPA recommended Point Count method. Any material that has greater than 1% asbestos content is considered to be an Asbestos Containing Material (ACM). These materials are regulated by both OSHA and the EPA and must be treated accordingly. Results are related to only to samples that were tested.

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
 38900 Huron River Drive
 Romulus, MI 48174

Location :

1042 Dakin St, Lansing, MI 48912

ETC Job : 200410

Client Project : N/A

Date Collected : 12/15/2017

Date Received : 12/19/2017

Date Analyzed : 12/20/2017

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
640822 09B 4 S Floor Analyst: Liliane Mason	Linoleum	Grey Fibrous Homogenous	20% Cellulose	80% Other	None Detected
640823 10A 4 N Floor Analyst: Liliane Mason	Linoleum	Brown Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
640824 10B 4 S Floor Analyst: Liliane Mason	Linoleum	Brown Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
640825 11A N 7 Wall Analyst: Liliane Mason	Concrete Block	Grey Non-Fibrous Homogenous	1% Cellulose	99% Other	None Detected
640826 11B S 8 Wall Analyst: Liliane Mason	Concrete Block	Grey Non-Fibrous Homogenous	1% Cellulose	99% Other	None Detected
640827 12A N 7 Wall Analyst: Liliane Mason	Mortar	White Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
640828 12B S 8 Wall Analyst: Liliane Mason	Mortar	White Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected

ETL, Inc. maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced without written approval by ETL, Inc. Test Method EPA 600/R-93-116 & EPA 600/M4-82/020 or NYSDOH-ELAP item 198.1 and/or 198.6 was used to analyze all samples. Matrix interference and/or resolution limits (i.e. detecting asbestos in non-friable organically bound materials) may yield false results in certain circumstances. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing. Interpretation and use of test results are the responsibility of the client. ETL, Inc. is not responsible for the accuracy of the results when requested to physically separate and analyze layered samples. Any PLM results below 10% should be re-analyzed using the EPA recommended Point Count method. Any material that has greater than 1% asbestos content is considered to be an Asbestos Containing Material (ACM). These materials are regulated by both OSHA and the EPA and must be treated accordingly. Results are related to only to samples that were tested.

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
 38900 Huron River Drive
 Romulus, MI 48174

Location :

1042 Dakin St, Lansing, MI 48912

ETC Job : 200410

Client Project : N/A

Date Collected : 12/15/2017

Date Received : 12/19/2017

Date Analyzed : 12/20/2017

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
640829 13A 7 W Floor Analyst: Liliane Mason	Poured Cement	Grey Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
640830 13B 8 N Floor Analyst: Liliane Mason	Poured Cement	Grey Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
640831 14A 14 W Floor Analyst: Liliane Mason	Blown-In Insulation	Brown Fibrous Homogenous	60% Cellulose	40% Other	None Detected
640832 14B 14 E Floor Analyst: Liliane Mason	Blown-In Insulation	Brown Fibrous Homogenous	60% Cellulose	40% Other	None Detected
640833 15A 5 W Floor Analyst: Liliane Mason	Linoleum	Black Fibrous Homogenous	40% Cellulose	60% Other	None Detected
640834 15B 5 E Floor Analyst: Liliane Mason	Linoleum	Black Fibrous Homogenous	40% Cellulose	60% Other	None Detected
640835 16A E Ext Analyst: Liliane Mason	House Wrap	Tan Fibrous Homogenous	70% Cellulose	30% Other	None Detected

ETL, Inc. maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced without written approval by ETL, Inc. Test Method EPA 600/R-93-116 & EPA 600/M4-82/020 or NYSDOH-ELAP item 198.1 and/or 198.6 was used to analyze all samples. Matrix interference and/or resolution limits (i.e. detecting asbestos in non-friable organically bound materials) may yield false results in certain circumstances. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing. Interpretation and use of test results are the responsibility of the client. ETL, Inc. is not responsible for the accuracy of the results when requested to physically separate and analyze layered samples. Any PLM results below 10% should be re-analyzed using the EPA recommended Point Count method. Any material that has greater than 1% asbestos content is considered to be an Asbestos Containing Material (ACM). These materials are regulated by both OSHA and the EPA and must be treated accordingly. Results are related to only to samples that were tested.

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
38900 Huron River Drive
Romulus, MI 48174

Location :
1042 Dakin St, Lansing, MI 48912

ETC Job : 200410
Client Project : N/A
Date Collected : 12/15/2017
Date Received : 12/19/2017
Date Analyzed : 12/20/2017

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
640836 16B S Ext Analyst: Liliane Mason	House Wrap	Tan Fibrous Homogenous	70% Cellulose	30% Other	None Detected
640837 17A E Ext Layer-1 Analyst: Liliane Mason	Shingle Siding	Black Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
640837 17A E Ext Layer-2 Analyst: Liliane Mason	Backing	Tan Fibrous Homogenous	70% Cellulose	30% Other	None Detected
640838 17B S Ext Layer-1 Analyst: Liliane Mason	Shingle Siding	Black Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
640838 17B S Ext Layer-2 Analyst: Liliane Mason	Backing	Tan Fibrous Homogenous	70% Cellulose	30% Other	None Detected
640839 18A E Ext Roof Analyst: Liliane Mason	Asphalt Roof Shingle	Black Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected
640840 18B S Ext Roof Analyst: Liliane Mason	Asphalt Roof Shingle	Black Non-Fibrous Homogenous	2% Cellulose	98% Other	None Detected

Polarized Light Microscopy Asbestos Analysis Report

To : Environmental Testing And Consulting Inc.
 38900 Huron River Drive
 Romulus, MI 48174

Location :

1042 Dakin St, Lansing, MI 48912

ETC Job : 200410

Client Project : N/A

Date Collected : 12/15/2017

Date Received : 12/19/2017

Date Analyzed : 12/20/2017

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Asbestos
--------	-------------	------------	-----------	---------------	------------



Lab Supervisor/Other Signatory



Analyst: Liliane Mason

400 Point Count Results by EPA 600/R-93/116 PLM (denoted by "PC")

Item 198.1: PLM Methods for Identifying and Quantitating Asbestos in Bulk Samples

Item 198.6: PLM Methods for Identifying and Quantitating Asbestos in Non-Friable Organically Bound Bulk Samples

EPA 600/R-93/116: Method for Determination of Asbestos in Bulk Building Materials

EPA 600/M4-82-020: Interim Method for Determination of Asbestos in Bulk Insulation Samples

ETL, Inc. maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced without written approval by ETL, Inc. Test Method EPA 600/R-93-116 & EPA 600/M4-82/020 or NYSDOH-ELAP item 198.1 and/or 198.6 was used to analyze all samples. Matrix interference and/or resolution limits (i.e. detecting asbestos in non-friable organically bound materials) may yield false results in certain circumstances. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing. Interpretation and use of test results are the responsibility of the client. ETL, Inc. is not responsible for the accuracy of the results when requested to physically separate and analyze layered samples. Any PLM results below 10% should be re-analyzed using the EPA recommended Point Count method. Any material that has greater than 1% asbestos content is considered to be an Asbestos Containing Material (ACM). These materials are regulated by both OSHA and the EPA and must be treated accordingly. Results are related to only to samples that were tested.

ENVIRONMENTAL TESTING LABORATORIES, INC

38900 HURON RIVER DRIVE
 ROMULUS, MICHIGAN 48174
 (734) 955-6600
 FAX: (734) 992-2261
 www.2etl.com

**Bulk Asbestos
 Chain of Custody**

ETL Project #: 200410

Client: ETC	Contact: Phone: (734) 955-6600	Project Location/Name: 1042 Dakin
Address: 721 N. Capitol Ave. Suite 3, Lansing, MI 48906	Fax: (734) 955-6604 E-mail: results@2etl.com	
Please Provide Results: <input type="checkbox"/> Email <input type="checkbox"/> Fax <input type="checkbox"/> Verbal <input type="checkbox"/> Other _____		Client Project #: 200410 Date Sampled: 12/15/17

Turnaround Time (TAT): RUSH Same Day 24 hr 48 hr Standard (3+ days) Other _____

PLM Instructions
(Check all that apply)

<input checked="" type="checkbox"/> PLM EPA600/R-93/116, 1993 (Standard method)	<input checked="" type="checkbox"/> Stop at 1st Positive - Clearly mark Homogenous Group
<input checked="" type="checkbox"/> Point Counting: 400 Points * NO	<input type="checkbox"/> Soil or Vermiculite Analysis *
<input type="checkbox"/> PLM Non-Building Material (Dust, Wipe, Tape)	

* Additional charge and turnaround may be required

Lab ID	Sample ID	Sample Location	Material Description
	01 ABCDE		
	02 ABC		
	03 AB		
	18 AB		

	Name/Organization	Date	Time
Relinquished (Name/Organization):	Bozle Wilko	12/15/17	
Received (Name/ETL):	Brittany Walls	12/19/17	am/pm
Stereoscopical Analysis (Name/ETL):	Leticia...	12/19/17	am/pm
Sample Login (Name/ETL):	Brittany Walls	12/19/17	am/pm
Analysis (Name/ETL):	Bozle Wilko		am/pm
QA/QC Review (Name/ETL):	R J	12/19/17	am/pm

Special Instructions: Please point count anything less than 30% if positive!

Remarks:

Asbestos Material Sampling Summary Sheet

Surfacing materials

Revision date 5/7/2015

Job #:	Building: 1042 Daken				Date:	12/15/17	Material Located throughout bldg (Please List all Rooms)	Quantity	Picture #
Material no.	Material Description	Friable (F) / Non-Friable (NF)	Sample Letter	Sample Location					
01	Material: Plaster grey	N	A	1 N Wall	640801				
			B	5 W Wall	803				
			C	2 E Wall	803				
			D	9 W Wall	804				
			E	11 W Wall	805				
	Material:						throughout	4500 2500	
	Material:								
	Material:								

<1000 SF = 3 samples

1000 - <5000 = 5 samples

Asbestos Material Sampling Summary Sheet TSI (Thermal System Insulation) materials

Revision date 5/7/2015

Job #:	Building: <i>W12 DAKin</i>		Date: <i>12/15/17</i>	Material Located throughout bldg (Please List all Rooms)	Quantity	Picture #
Material no.	Material Description	Friable (F) / Non-Friable (NF)	Sample Letter	Sample Location		
<i>02</i>	Material: <i>Duct wrap</i> Description: <i>white</i>	<i>Y</i>	<i>A</i>	<i>10 E Wall</i>	<i>10</i>	
			<i>B</i>	<i>10 E Wall</i>	<i>4</i>	
			<i>C</i>	<i>10 E Wall</i>	<i>LF</i>	
	Material: Description:					
	Material: Description:					
	Material: Description:					
	Material: Description:					
	Material: Description:					
	Material: Description:					
	Material: Description:					

3 samples with the exception of patches less than 6 LF or 6 SF, then only 1 sample

Asbestos Material Sampling Summary Sheet Miscellaneous materials

Revision date 5/7/2015

Job #:	200410		Building:	1042 DAKIN		Date:	12/15/17		
Material no.	Material Description	Friable (F) / Non-Friable (NF)	Sample Letter	Sample Location	Material Located throughout bldg (Please List all Rooms)	Quantity	Picture #		
03	Material: Dry wall	N	A	1 E Wall	throughout	2500			
	Description: white		B	2 E Wall					
04	Material: type	Y	A	1 E Wall	throughout	512 LF			
	Description: white		B	2 E Wall					
05	Material: m/d	Y	A	1 E Wall	throughout	512 LF			
	Description: grey		B	2 E Wall					
06	Material: Flooring	N	A	1 E floor	1	540			
	Description: tan		B	1 W floor					
07	Material: Limestone	N	A	3 S floor	3	144			
	Description: Grey		B	3 N floor					
08	Material: 12x12 tile	N	A	2 S floor	3	144			
	Description: tan		B	3 N floor					
09	Material: Limestone	N	A	4 N floor	4	180			
	Description: Grey		B	4 S floor					
10	Material: Limestone	N	A	4 N floor	4	180			
	Description: Brown		B	4 S floor					
11	Material: Con. c. ret	N	A	4 N 7 wall	4	180			
	Description: Grey		B	4 N 8 wall					
12	Material: mortar	N	A	4 N 7 wall	4	180			
	Description: white		B	4 N 8 wall					

2 samples

4

Asbestos Material Sampling Summary Sheet

Miscellaneous materials

Revision date 5/7/2015

Job #:	200HW		Building: 1042 DAKIN		Date: 12/15/19			
	Material no.	Material Description	Friable (F) / Non-Friable (NF)	Sample Letter	Sample Location	Material Located throughout bldg (Please List all Rooms)	Quantity	Picture #
13	Material: Poured cement		N	A	7 W floor	7/8	720	
	Description	Grey		B	8 N floor			
14	Material: Blown in		Y	A	14 W floor	14	81	
	Description	Grey		B	14 E floor			
15	Material: Limestone		N	A	5 W floor	5	54	
	Description	Black		B	5 E floor			
16	Material: House wrap		H	A	5 E EXT	ext	1856	
	Description	tan		B	5 E EXT			
17	Material: Shingle siding		N	A	5 E EXT	ext	1856	
	Description	Black/Green		B	5 E EXT			
18	Material: Asphalt Roof Shingle		N	A	5 E EXT	ext	720	
	Description	Black		B	5 E EXT			
	Material: Description			A				
	Material: Description			B				
	Material: Description			A				
	Material: Description			B				
	Material: Description			A				
	Material: Description			B				
	Material: Description			A				
	Material: Description			B				

Attachment:

Inspection Procedures

Pre-Demolition Environmental Inspection Procedures

HAZARDOUS MATERIALS INSPECTION

A table showing hazardous materials, above the household quantity limitations, found at the house is included as **Table 1: Hazardous Materials**. This table lists non-asbestos materials that may be hazardous and require special handling and disposal requirements. Items that might be in this category include: mercury switches, fluorescent lighting tubes and ballasts, halogen lights, Freon in refrigeration units, pesticides, herbicides, paints, solvents, etc.

Under the Resource Conservation and Recovery Act (RCRA) that addresses hazardous wastes, there is a residential household quantity exclusion. Materials are listed in Table I if they are present in quantities larger than what would typically be expected to be used and disposed in a normal household, and/or may require special handling and disposal requirements, such as: paints, solvents, adhesives, oils, tires, large circuit boards (such as televisions, computers, and security systems), prescription drugs, and syringes. On the other hand, if there were only household sized containers of maintenance, cleaning, non-prescription health and personal hygiene products, radios, and controllers present, as would be found in most homes, these materials would not be listed.

Fluorescent lighting systems have ballasts that have the potential to contain polychlorinated biphenyls (PCBs). Although PCBs are no longer commercially produced in the United States, they may be present in U.S. products that were produced prior to 1979, and may still be commercially available from other countries. Fluorescent bulbs, thermostats, and thermometers may contain mercury and can be treated as Universal Waste, which are streamlined standards for managing common types of hazardous waste.

If obtained, photographs of hazardous materials for the above referenced property are included in **Attachment: Site Photographs**.

ASBESTOS CONTAINING BUILDING MATERIAL INSPECTION

The property was inspected for the presence of asbestos-containing materials (ACMs) in order to meet the requirements of 40 CFR, Part 61, Subpart M, National Emissions Standards for Hazardous Air Pollutants (NESHAP).

Asbestos Inspection

The property was inspected for the presence of suspected ACMs. Typical building materials that may contain asbestos included drywall, plaster, stucco, floor tiles, roofing felt and shingles, ceiling tiles, insulation, pipe insulation, and duct insulation.

Sample Collection

Representative bulk samples of suspect asbestos containing building materials were randomly collected within each building area. The materials sampled were broken down into distinct homogenous (similar) materials. Homogenous material determination was based on the following criteria:

- Similar physical characteristics (same color and texture, etc.)
- Application (sprayed-on, troweled-on, assembly into a system etc.)
- Material function (Thermal insulation, floor tile, wallboard system etc.)

Pre-Demolition Environmental Inspection Procedures

At least two samples of each suspected asbestos containing material identified during the inspection was collected. For surfacing materials (sprayed and/or troweled on) a minimum of three samples were collected for areas that contained less than 1000 square feet of the material; 5 samples were collected for materials 1000 to 5000 square feet, and 7 samples were taken for areas greater than 5000 square feet. A Michigan Accredited Asbestos Inspector collected representative samples of each suspected ACM. Each sample was placed into a sealed plastic bag and labeled. A description of the material and location of the sample collected was recorded in the field notes. The total quantity of each suspected ACM was estimated and recorded in the field notes.

A listing of suspect ACMs at this property that were sampled and sent to the laboratory for analysis is included in **Table 2**. A copy of a floor plan showing sample locations is included in **Attachment: Site Drawing**.

Laboratory Analysis / Results

Each sample of suspect ACM collected at this property was analyzed for asbestos content using polarized light microscopy (PLM) by a NVLAP and NIST accredited laboratory in accordance with 40 CFR Ch. I (1-1-87 Edition) Part 763, Subpart F, Appendix A, pp. 293-299. Asbestos containing materials are defined as materials that contain greater than one percent (>1%) asbestos.

Each sample collected for analysis was delivered to either IATL (International Asbestos Testing Laboratories), 9000 Commerce Parkway, Suite B, Mt. Laurel, NJ 08054, ETL (Environmental Testing Laboratories), 38900 W. Huron River Drive, Suite 200, Romulus, MI 48174, and/or ACM Engineering & Environmental Services, 26598 US Highway 20 West, South Bend, IN 46628. Laboratory results are included in **Attachment: Laboratory Analytical Results**.

SIGNATURE

This report was prepared based on the site conditions that existed at the time of the inspection, sample collection, and the laboratory analytical results.



Prepared by: _____

Wade Wiltse, Michigan Certified Asbestos Inspector (s)

Michigan Accreditation Number (s) A-51051